

CATHY WEVER

Equipment	Model/Serial	Location	What it Serves	Time Spent	Filters	Belts	Repairs Needed or Repaired
HRU	Engair SH400-0 / 39305			1.5hrs	(12of) 20x24x4 (6of) 20x20x4	(3of) 5V1250	Unable to access every compartment due to handles being broken off (9of) Handles need to be replaced (Very hot in Electrical Control Panel -recommend vent fan to keep it cooler - Completed
Exhaust Fan 1	Greenheck RSF10015X / 06E07638			30 min	(4of) 24x12	(1of) AX39	filters need to be replaced - Completed
Exhaust Fan 3	Greenheck SWB 210 4 CCW UB7 / 06E07454			30 min			
Exhaust Fan 5	Greenheck 6B0816X / 06E08942			20 min		(1of) 3L170	Belt needs to be replaced - Completed
ERV 2	Carnes WECC0318R2R2C1EE / 2331281.002			45 min			
HP 42	McQuay WFMS1015EZ00Z00AA11ZZB2 / AUBU061901939	IT Room		60 min	(1of) 16x20x1		
HP 51	FHP EM036-3CFC / NB103027	Second Floor		60 min	(1of) 24x24x1		
HP 60	McQuay WFMS036FZ00ZAA0011ZZA2 / AUBUD81801253	Mechanical Room	Music Room	60 min	(1of) 24x230x1		Water outlet rejecting heat well, called Mike from school board to confirm stated issues with BAS system - Condesate line kinked s/b replaced - Completed
Room 135		Electrical Room					No exhaust fan or cooling of any kind - no room sensors

Administrative 20 min