

SIR WILLIAM OSLER

Equipment	Manufacturer / Model/Serial	Location	What it Serves	Filters	Belts	Time Spent	Repairs Needed
Cooling Tower	BAC VFL09641P / U070339301				(5of) B131	60 min	
MUA	Venmar DF1000HE 12 / S0000596 00			(30of) 20x24x4	(3of) B72	60 min	Filters s/b replaced in a month / Gas piping needs to be painted as per TSSA Greased Bearings in Supply Air Fan - Completed
Ventilation Fan	Greenheck RSF 150 4X / 07 E07864	Mechanical Room		(8of) 16x20x1	3L580	45 min	Requires guarding as fan is located approx 2' from edge of roof - Completed
Exhaust Fan (EF6)	Greenheck 68 081 4X / 10881199 0705				(1of) 3L210	20 min	Belt needs to be replaced - Completed
Exhaust Fan	Greenheck SWB210 4 CW UB X / 07E07816					20 min	
Exhaust Fan	Greenheck 6B 0814X / 10881195 0705	Labelled EF2				15 min	
RTU 1	Trane YSC072A3RLA0KF0B00001A000 / 731101151L			(4of) 16x25x2		30 min	
RTU 2	Trane YHC033A3RLA13F0B000010000 / 731101052L					30 min	
Exhaust Fan 3	Greenheck SB0814X / 108811980705	Lower roof			(1of) 3L210	15 min	Needs new Belt - Completed
HPU	N/A	Stores Room		(1of) 16x20x1		45 min	
HPU 28	Carrier 50RDS060LDC50120 / 2907V33986	Room 108	Library East			30 min	
HPU 26	Carrier 50RDS060LD50120 / 2907V33985	Mechanical Room	Library West			30 min	
HPU 40	Carrier 50RVS030LDC50120 / 2907V34017		Stage Area			30 min	
HPU 29	Carrier 50RDS024LDC50120 / 2907V50RDS0	Library Work Room				30 min	Found compressor contactor contacts pitted and carboned up s/b replaced - Completed

Administrative 30 min