

## WINONA

Equipment	Manufacturer / Model/Serial	Location	What it Serves	Time Spent	Filters	Belts	Repairs Needed
HRU 1	EngAir FWA285-DG220-0 / B47266 HRU						
Exhaust Air Fan	N/A						Need new pulley belts (Belts 2of B96, Inside bearing NTN P23, Outside Bearing NRN P211V) - Completed
Supply Motor 1	N/A				(6of) 20x20x2 (21of) 20x24x2	(4of)B74	
AHU	Changeair CAE100A	Classroom 1,2,3,4,5,6			(12of) 16x20x1 (12of) 12x20x1		All filters need to be changed - Completed
Exhaust Fan 7	Pennbarray DXP8B / B11XZ28695	Upper Roof	Washroom Exhaust				
HP 1-22	Climatemaster TSD024AGD40CLUS / P11031099	Room 107					
HP 2-2	Climatemaster TCV024AGD40CLVS / P110331945	Room 229 (Now 2036)					
Cooling Tower	Evapco LSWE4-4K12 / 10-401780					B81	
HP 1-24	Climatemaster TSD060AGD40CLUS / P11032433	Room 108 Room 109	Staff Room Seryery				Unable to get unit running via T-stat (Kyle could not see unit on front end - Completed
Ductless Split	Carrier	Electrical Room	Staff Room				
RTU	Carrier 48TCEA052A1A0B0A0 / 3211C553211N	Lower Roof	Kindergarden		(2of) 16x25x2	(1of) A35	Needs new filters and belts replaced - Completed
RTU	Carrier 48TCAEO5A2A1A0B0A0 / 3211C553211		Kindergarden Area		(2of) 16x25x2	(1of) A35	
Exhaust Fan	Pennbarray DXP8R					Direct Drive	
<b>Administrative 20 min</b>							