

**HWDSB - High and Urgent Renewal Needs**

<b>Asset</b>	<b>Event</b>	<b>Priority</b>	<b>Year</b>	<b>Cost</b>
Cardinal Heights, Building ID 9072-1	Replacement [C201001 Interior Stair Construction - Original Building - stage only]	Urgent	2012	\$10,200
Cardinal Heights, Building ID 9072-1	Replacement [D501003 Main Switchboards Main Disconnect - Original Building]	Urgent	2012	\$73,440
Cardinal Heights, Building ID 9072-1	.Study [G30 Site Civil/Mechanical Utilities - Site]	High	2012	\$8,160
Cardinal Heights, Building ID 9072-1	Replacement [C3020 Floor Finishes - Vinyl Floor Tiles - Entire Building]	High	2012	\$204,000
Cardinal Heights, Building ID 9072-1	Replacement [D304007 Exhaust Systems - Original Building]	High	2012	\$128,520
Cardinal Heights, Building ID 9072-1	Replacement [D3050 Terminal & Package Units - Original Building]	High	2012	\$10,200
Cardinal Heights, Building ID 9072-1	Replacement [D3050 Terminal & Package Units Unit Ventilators - Original Building]	High	2012	\$15,300
Cardinal Heights, Building ID 9072-1	.Study [D304003 Heating/Chilling water distribution systems - Original Building]	High	2013	\$8,160
Cardinal Heights, Building ID 9072-1	Replacement [A1010 Standard Foundations - Original Building]	High	2013	\$10,200
Cardinal Heights, Building ID 9072-1	Replacement [C1030 Fittings - Lockers Remainder]	High	2013	\$91,800
Cardinal Heights, Building ID 9072-1	Replacement [D303099 Other Cooling Generating Systems]	High	2013	\$10,200
Cardinal Heights, Building ID 9072-1	Replacement [D304003 Heating/Chilling water distribution systems - Original Building]	High	2013	\$629,340
Cardinal Heights, Building ID 9072-1	Replacement [D3060 Controls & Instrumentation - Original Building]	High	2013	\$244,800
Cardinal Heights, Building ID 9072-1	Replacement [D501002 Secondary - Original Building]	High	2013	\$36,720
Cardinal Heights, Building ID 9072-1	Replacement [D501003 Main Switchboards Main Distribution Panel - Original Building]	High	2013	\$73,440
Cardinal Heights, Building ID 9072-1	Replacement [D502002 Lighting Equipment - Original Building]	High	2013	\$10,200
Cardinal Heights, Building ID 9072-1	Replacement [G30 Site Civil/Mechanical Utilities - Site]	High	2013	\$392,700
Cardinal Heights, Building ID 9072-1	Replacement - B2010 Exterior Walls - Pre-finished Metal Panels	High	2014	\$96,900
Cardinal Heights, Building ID 9072-1	Replacement [C3020 Floor Finishes - Concrete Floor]	High	2014	\$10,200
Cardinal Heights, Building ID 9072-1	Replacement[B101001 Structural Frame - Original Building]	High	2014	\$204,000

\$2,268,480

**HWDSB - High and Urgent Renewal Needs**

<b>Asset</b>	<b>Event</b>	<b>Priority</b>	<b>Year</b>	<b>Cost</b>
Eastmount Park, Building ID 9112-1	Replacement [D501003 Main Switchboards - Original Building]	High	2012	\$71,563
Eastmount Park, Building ID 9112-1	Study [D304003 Heating/Chilling water distribution systems]	High	2012	\$11,451
Eastmount Park, Building ID 9112-1	Replacement [D304003 Heating/Chilling water distribution systems]	High	2012	\$229,000
Eastmount Park, Building ID 9112-1	Replacement [B2030 Exterior Doors - Entire Building]	High	2012	\$57,250
Eastmount Park, Building ID 9112-1	Replacement [D3050 Terminal & Package Units]	High	2012	\$42,938
Eastmount Park, Building ID 9112-1	Replacement [D502002 Lighting Equipment - Original Building]	High	2012	\$7,157

\$419,359

**HWDSB - High and Urgent Renewal Needs**

<b>Asset</b>	<b>Event</b>	<b>Priority</b>	<b>Year</b>	<b>Cost</b>
Franklin Road, Building ID 9073-1	Replacement [D304003 Heating/Chilling water distribution systems - Original Building]	Urgent	2012	\$286,251
Franklin Road, Building ID 9073-1	Study [D304003 Heating/Chilling water distribution systems - Original Building]	Urgent	2012	\$7,157
Franklin Road, Building ID 9073-1	Major Repair [B2010 Exterior Walls - General]	High	2012	\$143,125
Franklin Road, Building ID 9073-1	Study [B2010 Exterior Walls - General]	High	2012	\$7,157
Franklin Road, Building ID 9073-1	Replacement [D501003 Main Switchboards - Original Building]	High	2012	\$21,469
Franklin Road, Building ID 9073-1	Replacement [D2020 Domestic Water Distribution - Original Building]	High	2012	\$143,125
Franklin Road, Building ID 9073-1	Study [D2020 Domestic Water Distribution - Original Building]	High	2012	\$7,157
Franklin Road, Building ID 9073-1	Study [G30 Site Civil/Mechanical Utilities - Site]	High	2012	\$7,157
Franklin Road, Building ID 9073-1	Replacement [G30 Site Civil/Mechanical Utilities - Site]	High	2012	\$214,688
Franklin Road, Building ID 9073-1	Replacement [C3020 Floor Finishes - General]	High	2012	\$114,501
Franklin Road, Building ID 9073-1	Replacement [D502001 Branch Wiring - Original Building]	High	2012	\$286,251
Franklin Road, Building ID 9073-1	Study [D502001 Branch Wiring - Original Building]	High	2012	\$71,563
Franklin Road, Building ID 9073-1	Replacement [G204007 Playing Fields]	High	2012	\$107,344
Franklin Road, Building ID 9073-1	Replacement [B2030 Exterior Doors - Original Building] [01.3-035 Exterior Door Hardware - Original Building]	High	2012	\$28,625
Franklin Road, Building ID 9073-1	Replacement [B2030 Exterior Doors - General]	High	2012	\$50,094
Franklin Road, Building ID 9073-1	Replacement [G204001 Fencing & Gates]	High	2012	\$28,625
Franklin Road, Building ID 9073-1	Replacement [G204005 Signage]	High	2012	\$21,469

\$1,545,758

**HWDSB - High and Urgent Renewal Needs**

<b>Asset</b>	<b>Event</b>	<b>Priority</b>	<b>Year</b>	<b>Cost</b>
George L. Armstrong, Building ID 9074-1	Study [G30 Site Civil/Mechanical Utilities - Site]	Urgent	2012	\$7,157
George L. Armstrong, Building ID 9074-1	Replacement [G30 Site Civil/Mechanical Utilities - Site]	Urgent	2012	\$200,376
George L. Armstrong, Building ID 9074-1	Replacement [B3010 Roof Coverings]	Urgent	2012	\$286,251
George L. Armstrong, Building ID 9074-1	Replacement [G204001 Fencing & Gates - Site]	High	2012	\$21,469
George L. Armstrong, Building ID 9074-1	Replacement [B2030 Exterior Doors]	High	2012	\$57,250
George L. Armstrong, Building ID 9074-1	Study [D2020 Domestic Water Distribution - orig & add 1]	High	2012	\$7,157
George L. Armstrong, Building ID 9074-1	Replacement [D2020 Domestic Water Distribution - orig & add 1]	High	2012	\$143,125
George L. Armstrong, Building ID 9074-1	Replacement [C3020 Floor Finishes]	High	2012	\$357,813
George L. Armstrong, Building ID 9074-1	Replacement [C3020 Floor Finishes - Addition 2]	High	2012	\$35,781
George L. Armstrong, Building ID 9074-1	Replacement [D304007 Exhaust Systems - Addition 1]	High	2012	\$4,294
George L. Armstrong, Building ID 9074-1	Replacement [D503004 Public Address Systems - Original Building]	High	2012	\$71,563
George L. Armstrong, Building ID 9074-1	Study [D502001 Branch Wiring - Original Building] [04.2-060 Cabling, Raceways & Bus Ducts -	High	2012	\$7,157
George L. Armstrong, Building ID 9074-1	Replacement [D502001 Branch Wiring - Original Building]	High	2012	\$143,125
George L. Armstrong, Building ID 9074-1	Replacement [C3030 Ceiling Finishes]	High	2012	\$128,813
George L. Armstrong, Building ID 9074-1	Replacement [C3010 Wall Finishes]	High	2012	\$71,563
George L. Armstrong, Building ID 9074-1	Replacement [D502002 Lighting Equipment]	High	2012	\$11,451
George L. Armstrong, Building ID 9074-1	Replacement [C3020 Floor Finishes - Addition 2]	High	2013	\$41,113

\$1,595,458

**HWDSB - High and Urgent Renewal Needs**

<b>Asset</b>	<b>Event</b>	<b>Priority</b>	<b>Year</b>	<b>Cost</b>
Linden Park, Building ID 9086-2	Replacement [B2020 Exterior Windows - Original Building]	High	2012	\$292,740
Linden Park, Building ID 9086-2	Major Repair [B2010 Exterior Walls]	High	2012	\$131,580
Linden Park, Building ID 9086-2	Study [B2010 Exterior Walls]	High	2012	\$15,300
Linden Park, Building ID 9086-2	Replacement [C3020 Floor Finishes - Vinyl Floor Tiles - Original Building]	High	2012	\$173,400
Linden Park, Building ID 9086-2	Replacement [D304003 Heating/Chilling water distribution systems - Heating piping system]	High	2013	\$219,300
Linden Park, Building ID 9086-2	.Study [304003 heating / chilling water distribution ststems - heating piping system]	High	2013	\$8,160
Linden Park, Building ID 9086-2	Replacement [B3010 Roof Coverings - Original Building - Section 101]	High	2013	\$520,200
Linden Park, Building ID 9086-2	Replacement [A1010 Standard Foundations - Parging - Original Building]	High	2013	\$10,200
Linden Park, Building ID 9086-2	Replacement [D302005 Auxiliary Equipment - HVAC pump]	High	2013	\$18,360
Linden Park, Building ID 9086-2	Replacement [D3050 Terminal & Package Units]	High	2013	\$204,000
Linden Park, Building ID 9086-2	Replacement [D502002 Lighting Equipment - Exterior lighting - Original Building]	High	2013	\$10,200

\$1,603,440

**HWDSB - High and Urgent Renewal Needs**

Asset	Event	Priority	Year	Cost
Pauline Johnson, Building ID 9072-2	Replacement [B2020 Exterior Windows - Original Building]	High	2012	\$157,438
Pauline Johnson, Building ID 9072-2	Replacement [B2030 Exterior Doors - Original Building]	High	2012	\$17,175
Pauline Johnson, Building ID 9072-2	Replacement [C1030 Fittings - Original Building]	High	2012	\$48,662
Pauline Johnson, Building ID 9072-2	Replacement [C3030 Ceiling Finishes - Original Building]	High	2012	\$128,813
Pauline Johnson, Building ID 9072-2	Replacement [D2010 Plumbing Fixtures - Original Building]	High	2012	\$57,250
Pauline Johnson, Building ID 9072-2	Replacement [D2020 Domestic Water Distribution - Original Building]	High	2012	\$99,070
Pauline Johnson, Building ID 9072-2	Replacement [D501003 Main Switchboards - Original Building]	High	2012	\$28,625
Pauline Johnson, Building ID 9072-2	Replacement [D502002 Lighting Equipment]	High	2012	\$21,469
Pauline Johnson, Building ID 9072-2	Replacement [D503004 Public Address Systems - Original Building] Communications System	High	2012	\$71,563
Pauline Johnson, Building ID 9072-2	Replacement [G2020 Parking Lots]	High	2012	\$35,781
Pauline Johnson, Building ID 9072-2	Study [D2020 Domestic Water Distribution - Original Building]	High	2012	\$7,157

\$673,003

**HWDSB - High and Urgent Renewal Needs**

<b>Asset</b>	<b>Event</b>	<b>Priority</b>	<b>Year</b>	<b>Cost</b>
Queensdale, Building ID 9130-1	Replacement [G30 Site Civil/Mechanical Utilities - Site]	Urgent	2012	\$107,344
Queensdale, Building ID 9130-1	Study [G30 Site Civil/Mechanical Utilities - Site]	Urgent	2012	\$7,157
Queensdale, Building ID 9130-1	Replacement [B2030 Exterior Doors]	High	2012	\$57,250
Queensdale, Building ID 9130-1	Replacement [B3010 Roof Coverings]	High	2012	\$500,939
Queensdale, Building ID 9130-1	Replacement [C1020 Interior Doors]	High	2012	\$57,250
Queensdale, Building ID 9130-1	Replacement [C3010 Wall Finishes]	High	2012	\$71,563
Queensdale, Building ID 9130-1	Replacement [C3030 Ceiling Finishes - Addition 1]	High	2012	\$42,938
Queensdale, Building ID 9130-1	Replacement [D2020 Domestic Water Distribution]	High	2012	\$100,187
Queensdale, Building ID 9130-1	Replacement [D502002 Lighting Equipment - Original Building]	High	2012	\$7,157
Queensdale, Building ID 9130-1	Replacement [G2020 Parking Lots]	High	2012	\$21,469
Queensdale, Building ID 9130-1	Replacement [G204007 Playing Fields - Site]	High	2012	\$42,938
Queensdale, Building ID 9130-1	Study [D2020 Domestic Water Distribution]	High	2012	\$7,157

\$1,023,349

**HWDSB - High and Urgent Renewal Needs**

<b>Asset</b>	<b>Event</b>	<b>Priority</b>	<b>Year</b>	<b>Cost</b>
Ridgemount, Building ID 9134-1	Replacement [D3020 Heat Generating Systems - Original Building]	Urgent	2012	\$10,200
Ridgemount, Building ID 9134-1	Replacement [D2020 Domestic Water Distribution - Original Building]	High	2012	\$10,200
Ridgemount, Building ID 9134-1	.Study [D304003 Heating/Chilling water distribution systems- Original]	High	2013	\$8,160
Ridgemount, Building ID 9134-1	.Study [D4020 Standpipe Systems - Original Building]	High	2013	\$8,160
Ridgemount, Building ID 9134-1	Replacement [A1010 Standard Foundations - Parging]	High	2013	\$10,200
Ridgemount, Building ID 9134-1	Replacement [D304003 Heating/Chilling water distribution systems- Original]	High	2013	\$209,100
Ridgemount, Building ID 9134-1	Replacement [D3050 Terminal & Package Units - Original Building]	High	2013	\$72,420
Ridgemount, Building ID 9134-1	Replacement [D3060 Controls & Instrumentation - Original Building]	High	2013	\$244,800
Ridgemount, Building ID 9134-1	Replacement [D4020 Standpipe Systems - Original Building]	High	2013	\$31,620
Ridgemount, Building ID 9134-1	Replacement [D501003 Main Switchboards - Original Building]	High	2013	\$146,880
Ridgemount, Building ID 9134-1	Replacement [D502002 Lighting Equipment - Original Building - Ballast upgrade 1998]	High	2013	\$234,600

\$986,340