

School	Technical Category	Capital Renewal Description	Projected Implementation Year	Estimated Cost
Dalewood, 9108	03.1-010 (HW/S) Boilers - Original Building	Repair [03.1-010 (HW/S) Boilers - Original Building]	2010	\$26,426
Dalewood, 9108	04.2-060 Cabling, Raceways & Bus Ducts - Original Building	Replace [04.2-060 Cabling, Raceways & Bus Ducts - Original Building]	2010	\$118,919
Dalewood, 9108	03.3-050 Plumbing Piping Systems - Original Building	Replace [03.3-050 Plumbing Piping Systems - Original Building]	2010	\$158,558
Dalewood, 9108	03.2 Control Systems	Replace controls.	2010	\$99,099
Dalewood, 9108	03.1-170 Heating & Cooling Piping Systems - Original Building	Replace [03.1-170 Heating & Cooling Piping Systems - Original Building]	2010	\$132,132
Dalewood, 9108	01.3-030 Exterior Doors - Original Building	Replace [01.3-030 Exterior Doors - Original Building]	2010	\$23,784
Dalewood, 9108	01.3-035 Exterior Door Hardware - Original Building	Replace [01.3-035 Exterior Door Hardware - Original Building]	2010	\$11,892
Dalewood, 9108	01.3-040 Windows - Original Building	Replace [01.3-040 Windows - Original Building]	2010	\$198,198
Dalewood, 9108	01.4 Roofing - Original Building	Replace [01.4 Roofing - Original Building] Sections 102, 301, 403	2010	\$191,368
Dalewood, 9108	01.4 Roofing - Original Building	Replace [01.4 Roofing - Original Building] Sections 101, 401, 402, 501, 502, 601, 701	2010	\$379,125
Dalewood, 9108	01.5-011 Moveable Partitions - Original Building	Replace [01.5-011 Moveable Partitions - Original Building]	2010	\$39,640
Dalewood, 9108	01.5-020 Millwork - Original Building	Replace [01.5-020 Millwork - Original Building]	2010	\$462,462
Dalewood, 9108	01.5-050 Interior Doors - Original Building	Replace [01.5-050 Interior Doors - Original Building]	2010	\$165,165
Dalewood, 9108	01.5-055 Interior Door Hardware - Original Building	Replace [01.5-055 Interior Door Hardware - Original Building]	2010	\$59,459
Dalewood, 9108	01.5-060C01 Paint Wallcovering - Original Building	Replace [01.5-060C01 Paint Wallcovering - Original Building]	2010	\$66,066
Dalewood, 9108	01.5-060C04 Ceramic Wall Tile - Original Building	Replace [01.5-060C04 Ceramic Wall Tile - Original Building]	2010	\$39,640
Dalewood, 9108	01.5-060C08 Glazed Wall Coatings - Original Building	Replace [01.5-060C08 Glazed Wall Coatings - Original Building]	2010	\$33,033
Dalewood, 9108	01.5-070C04 Carpeting - Original Building	Replace [01.5-070C04 Carpeting - Original Building]	2010	\$39,640
Dalewood, 9108	01.5-070C05 Vinyl Floor Tile - Original Building	Replace [01.5-070C05 Vinyl Floor Tile - Original Building]	2010	\$52,853
Dalewood, 9108	01.5-080C03 Lath & Plaster Ceiling - Original Building	Replace [01.5-080C03 Lath & Plaster Ceiling - Original Building]	2010	\$66,066
Dalewood, 9108	01.5-100 Washroom Accessories - Original Building	Replace [01.5-100 Washroom Accessories - Original Building]	2010	\$59,459
Dalewood, 9108	01.6 Fittings & Equipment - Original Building	Replace [01.6 Fittings & Equipment - Original Building]	2010	\$39,640
Dalewood, 9108	03.1-160 Central Station AHU - Original Building	Replace [03.1-160 Central Station AHU - Original Building]	2010	\$264,264
Dalewood, 9108	03.1-190 Terminal Units - Original Building	Replace [03.1-190 Terminal Units - Original Building]	2010	\$158,558
Dalewood, 9108	03.1-200 Gas Piping System - Original Building	Replace [03.1-200 Gas Piping System - Original Building]	2010	\$26,426
Dalewood, 9108	03.1-260 Stacks & Breaching - Original Building	Replace [03.1-260 Stacks & Breaching - Original Building]	2010	\$19,820
Dalewood, 9108	03.2 Control Systems - Original Building	Replace [03.2 Control Systems - Original Building]	2010	\$394,765
Dalewood, 9108	03.3-010 Plumbing Fixtures - Original Building	Replace [03.3-010 Plumbing Fixtures - Original Building]	2010	\$132,132
Dalewood, 9108	03.3-030 Domestic Water Heaters - Original Building	Replace [03.3-030 Domestic Water Heaters - Original Building]	2010	\$3,964
Dalewood, 9108	03.3-040 Plumbing Pumps - Original Building	Replace [03.3-040 Plumbing Pumps - Original Building]	2010	\$14,764
Dalewood, 9108	04.1-010 Primary Switchgear - Original Building	Replace [04.1-010 Primary Switchgear - Original Building]	2010	\$79,279
Dalewood, 9108	04.1-020 Primary Transformer - Original Building	Replace [04.1-020 Primary Transformer - Original Building]	2010	\$92,492
Dalewood, 9108	04.2-010 Secondary Switchgear - Original Building	Replace [04.2-010 Secondary Switchgear - Original Building]	2010	\$99,099
Dalewood, 9108	04.6-010 Clock Systems - Original Building	Replace [04.6-010 Clock Systems - Original Building]	2010	\$13,213
Dalewood, 9108	01.2-010 Structural Framing - Original Building	Study Structural Framing	2010	\$6,607
Dalewood, 9108	03.1-170 Heating & Cooling Piping Systems - Original Building	Study [03.1-170 Heating & Cooling Piping Systems - Original Building]	2010	\$6,607
Dalewood, 9108	03.3-050 Plumbing Piping Systems - Original Building	Study [03.3-050 Plumbing Piping Systems - Original Building]	2010	\$6,607
Dalewood, 9108	04.2-060 Cabling, Raceways & Bus Ducts - Original Building	Study [04.2-060 Cabling, Raceways & Bus Ducts - Original Building]	2010	\$6,607
Dalewood, Campus ID 9108 - Site	00.1-010 Underground Utilities - Site	Replace [00.1-010 Underground Utilities - Site]	2010	\$198,198
Dalewood, Campus ID 9108 - Site	00.2-010 Paved Parking Lots - Site	Replace [00.2-010 Paved Parking Lots - Site]	2010	\$33,033
Dalewood, Campus ID 9108 - Site	00.2-012 Paved Playgrounds - Site	Replace [00.2-012 Paved Playgrounds - Site]	2010	\$26,426
Dalewood, Campus ID 9108 - Site	00.1-010 Underground Utilities - Site	Study - Underground Utilities - Site	2010	\$6,607
Dalewood, 9108	03.1-210 Chemical Feed System - Original Building	Replace [03.1-210 Chemical Feed System - Original Building]	2012	\$16,604
Dalewood, 9108	01.5-070C04 Carpeting - Original Building	Replace [01.5-070C04 Carpeting - Original Building]	2013	\$39,640
Dalewood, 9108	03.3-030 Domestic Water Heaters - Original Building	Replace [03.3-030 Domestic Water Heaters - Original Building]	2013	\$22,147
Dalewood, 9108	04.3-020 Exterior Lighting - Original Building	Replace [04.3-020 Exterior Lighting - Original Building]	2013	\$14,834
Dalewood, 9108	04.4 Electrical Service Ground - Original Building	Replace [04.4 Electrical Service Ground - Original Building]	2013	\$22,488
Dalewood, Campus ID 9108 - Site	00.1-016 Soft Landscaping - Site	Replace [00.1-016 Soft Landscaping - Site]	2013	\$9,249
Dalewood, 9108	01.5-060C01 Paint Wallcovering - Original Building	Replace [01.5-060C01 Paint Wallcovering - Original Building]	2014	\$66,066
Dalewood, 9108	01.5-070C07 Hardwood - Original Building	Replace [01.5-070C07 Hardwood - Original Building]	2014	\$52,853
Dalewood, 9108	01.5-110 Interior Stairs - Original Building	Replace [01.5-110 Interior Stairs - Original Building]	2014	\$66,066

ReCAPP Event Listing: 2003 - 2021

May 6, 2011

Dalewood, 9108	03.1-010 (HW/S) Boilers - Original Building	Replace [03.1-010 (HW/S) Boilers - Original Building]	2015	\$151,258
Dalewood, 9108	03.1-210 Chemical Feed System - Original Building	Replace [03.1-210 Chemical Feed System - Original Building]	2016	\$16,604
Dalewood, 9108	04.3-040 Emergency Lighting - Original Building	Replace [04.3-040 Emergency Lighting - Original Building]	2016	\$88,588
Dalewood, Campus ID 9108 - Site	00.3-012 Unpaved Playgrounds - Site	Replace [00.3-012 Unpaved Playgrounds - Site]	2016	\$10,571
Dalewood, 9108	03.1-180 HVAC Pumps - Original Building	Replace [03.1-180 HVAC Pumps - Original Building]	2017	\$18,868
Dalewood, 9108	03.5-050 Fire Extinguishers - Original Building	Replace [03.5-050 Fire Extinguishers - Original Building]	2017	\$18,093
Dalewood, 9108	04.7 Information Technology Systems - Original Building	Replace [04.7 Information Technology Systems - Original Building]	2017	\$32,482
Dalewood, 9108	01.3-035 Exterior Door Hardware - Original Building	Replace [01.3-035 Exterior Door Hardware - Original Building]	2019	\$10,571
Dalewood, 9108	01.5-060C08 Glazed Wall Coatings - Original Building	Replace [01.5-060C08 Glazed Wall Coatings - Original Building]	2019	\$33,033
Dalewood, 9108	01.5-100 Washroom Accessories - Original Building	Replace [01.5-100 Washroom Accessories - Original Building]	2019	\$59,459
Dalewood, 9108	03.1-160 Central Station AHU - Original Building	Replace [03.1-160 Central Station AHU - Original Building]	2019	\$625,962
Dalewood, 9108	01.5-055 Interior Door Hardware - Original Building	Replace [01.5-055 Interior Door Hardware - Original Building]	2020	\$59,459
Dalewood, 9108	01.5-090 Window Coverings - Original Building	Replace [01.5-090 Window Coverings - Original Building]	2020	\$99,099
Dalewood, 9108	03.1-040 (HW/S) Heat Exchangers - Original Building	Replace [03.1-040 (HW/S) Heat Exchangers - Original Building]	2020	\$17,987
			<b>Total</b>	<b>\$5,604,073</b>

School	Technical Category	Capital Renewal Description	Projected Implementation Year	Estimated Cost
George R Allan, Campus ID 9075 - Site	00.1-010 Underground Utilities - Site	Replace [00.1-010 Underground Utilities - Site]	2010	\$198,198
George R Allan, Campus ID 9075 - Site	00.1-010 Underground Utilities - Site	Study - Underground Utilities - Site	2010	\$6,607
George R Allan, Campus ID 9075 - Site	00.2-012 Paved Playgrounds - Site	Replace [00.2-012 Paved Playgrounds - Site]	2010	\$59,459
George R Allan, Campus ID 9075 - Site	00.3-013 Unpaved Sports & Recreational Spaces	Replace Unpaved Sports & Recreational Spaces	2010	\$33,033
George R Allan, 9075	01.3-010 Exterior Walls - Original Building	Replace [01.3-010 Exterior Walls - Original Building]	2010	\$825,825
George R Allan, 9075	01.3-030 Exterior Doors - Original Building	Replace [01.3-030 Exterior Doors - Original Building]	2010	\$26,426
George R Allan, 9075	01.4 Roofing - Addition 1	Replace [01.4 Roofing - Addition 1] Section 302	2010	\$38,886
George R Allan, 9075	01.4 Roofing - Addition 2	Replace [01.4 Roofing - Addition 2] Sections 101, 201	2010	\$74,529
George R Allan, 9075	01.4 Roofing - Original Building	Replace [01.4 Roofing - Original Building] Sections 301, 303, 304, 401, 402	2010	\$101,736
George R Allan, 9075	01.5-010 Partitions - Original Building	Replace [01.5-010 Partitions - Original Building]	2010	\$231,231
George R Allan, 9075	01.5-020 Millwork - Addition 2	Replace [01.5-020 Millwork - Addition 2]	2010	\$99,099
George R Allan, 9075	01.5-020 Millwork - Original Building	Replace [01.5-020 Millwork - Original Building]	2010	\$165,165
George R Allan, 9075	01.5-050 Interior Doors - Original Building	Replace [01.5-050 Interior Doors - Original Building]	2010	\$52,853
George R Allan, 9075	01.5-060C01 Paint Wallcovering	Replace [01.5-060C01 Paint Wallcovering]	2010	\$92,492
George R Allan, 9075	01.5-060C04 Ceramic Wall Tile - Original Building	Replace [01.5-060C04 Ceramic Wall Tile - Original Building]	2010	\$66,066
George R Allan, 9075	01.5-070C03 Terrazzo - Addition 1	Replace [01.5-070C03 Terrazzo - Addition 1]	2010	\$26,426
George R Allan, 9075	01.5-070C04 Carpeting -General	Replace [01.5-070C04 Carpeting - Addition 2]	2010	\$79,279
George R Allan, 9075	01.5-070C05 Vinyl Floor Tile - Addition 2	Replace [01.5-070C05 Vinyl Floor Tile - Addition 2]	2010	\$26,426
George R Allan, 9075	01.5-080C03 Lath & Plaster Ceiling - Original Building	Replace [01.5-080C03 Lath & Plaster Ceiling - Original Building]	2010	\$66,066
George R Allan, 9075	01.5-100 Washroom Accessories - Original Building	Replace [01.5-100 Washroom Accessories - Original Building]	2010	\$19,820
George R Allan, 9075	01.5-110 Interior Stairs - Original Building	Replace [01.5-110 Interior Stairs - Original Building]	2010	\$26,426
George R Allan, 9075	01.6 Fittings & Equipment - Original Building	Replace [01.6 Fittings & Equipment - Original Building]	2010	\$26,426
George R Allan, 9075	03.1-220 Duct Systems - Original Building	Replace [03.1-220 Duct Systems - Original Building]	2010	\$195,407
George R Allan, 9075	03.1-250 Ventilation Fans - Original Building	Replace [03.1-250 Ventilation Fans - Original Building]	2010	\$18,554
George R Allan, 9075	03.3-010 Plumbing Fixtures - Addition 1	Replace [03.3-010 Plumbing Fixtures - Addition 1]	2010	\$72,921
George R Allan, 9075	03.3-010 Plumbing Fixtures - Original Building	Replace [03.3-010 Plumbing Fixtures - Original Building]	2010	\$132,132
George R Allan, 9075	03.3-030 Domestic Water Heaters - Original Building	Replace [03.3-030 Domestic Water Heaters - Original Building]	2010	\$2,643
George R Allan, 9075	03.3-050 Plumbing Piping Systems - Original Building	Replace the plumbing piping systems.	2010	\$158,558
George R Allan, 9075	03.3-050 Plumbing Piping Systems - Original Building	Study [03.3-050 Plumbing Piping Systems - Original Building]	2010	\$6,607
George R Allan, 9075	04.2-010 Secondary Switchgear	Replace secondary switchgear	2010	\$26,426
George R Allan, 9075	04.2-060 Cabling, Raceways & Bus Ducts - Addition 1	Replace [04.2-060 Cabling, Raceways & Bus Ducts - Addition 1]	2010	\$198,331
George R Allan, 9075	04.2-060 Cabling, Raceways & Bus Ducts - Addition 2	Replace [04.2-060 Cabling, Raceways & Bus Ducts - Addition 2]	2010	\$26,109
George R Allan, 9075	04.2-060 Cabling, Raceways & Bus Ducts - Original Building	Replace [04.2-060 Cabling, Raceways & Bus Ducts - Original Building]	2010	\$118,919
George R Allan, 9075	04.2-060 Cabling, Raceways & Bus Ducts - Original Building	Study [04.2-060 Cabling, Raceways & Bus Ducts - Original Building]	2010	\$6,607
George R Allan, 9075	04.3-040 Emergency Lighting - Addition 4	Replace [04.3-040 Emergency Lighting - Addition 4]	2010	\$9,973
George R Allan, 9075	04.3-040 Emergency Lighting - Original Building	Replace [04.3-040 Emergency Lighting - Original Building]	2010	\$39,640
George R Allan, 9075	01.6 Fittings & Equipment - Addition 2	Replace [01.6 Fittings & Equipment - Addition 1]	2011	\$19,820
George R Allan, 9075	01.5-070C03 Terrazzo - Original Building	Replace [01.5-070C03 Terrazzo - Original Building]	2012	\$66,066
George R Allan, 9075	01.5-070C07 Hardwood - stage	Replace [01.5-070C07 Hardwood - stage]	2012	\$52,853
George R Allan, 9075	01.5-090 Window Coverings - Addition 2	Replace [01.5-090 Window Coverings - Addition 4]	2012	\$52,853
George R Allan, 9075	03.3-010 Plumbing Fixtures - Addition 2	Replace [03.3-010 Plumbing Fixtures - Addition 2]	2012	\$7,833
George R Allan, 9075	03.3-010 Plumbing Fixtures - Addition 3	Replace [03.3-010 Plumbing Fixtures - Addition 3]	2012	\$26,343
George R Allan, 9075	03.3-050 Plumbing Piping Systems - Addition 1	Replace [03.3-050 Plumbing Piping Systems - Addition 1]	2012	\$85,073
George R Allan, 9075	03.3-050 Plumbing Piping Systems - Addition 2	Replace [03.3-050 Plumbing Piping Systems - Addition 2]	2012	\$8,433
George R Allan, 9075	04.3-010 Interior Lighting - Addition 3	Replace [04.3-010 Interior Lighting - Addition 3]	2012	\$48,237
George R Allan, 9075	04.3-040 Emergency Lighting - Addition 1	Replace [04.3-040 Emergency Lighting - Addition 1]	2012	\$15,959
George R Allan, 9075	01.5-055 Interior Door Hardware - Addition 2	Replace [01.5-055 Interior Door Hardware - Addition 2]	2013	\$13,213
George R Allan, 9075	01.5-070C04 Carpeting -General	Replace [01.5-070C04 Carpeting - Addition 2]	2013	\$39,640
George R Allan, 9075	01.5-080C02 Suspended Acoustic Panel Ceiling - 2	Replace [01.5-080C02 Suspended Acoustic Panel Ceiling - Addition 4]	2013	\$99,099
George R Allan, 9075	03.1-200 Gas Piping System - Original Building	Replace [03.1-200 Gas Piping System - Original Building]	2013	\$19,378
George R Allan, 9075	03.1-220 Duct Systems - Addition 1	Replace [03.1-220 Duct Systems - Addition 1]	2013	\$142,130

ReCAPP Event Listing: 2003 - 2021

May 6, 2011

George R Allan, 9075	03.3-010 Plumbing Fixtures - Addition 4	Replace [03.3-010 Plumbing Fixtures - Addition 4]	2013	\$45,572
George R Allan, 9075	03.3-050 Plumbing Piping Systems - Addition 3	Replace [03.3-050 Plumbing Piping Systems - Addition 3]	2013	\$30,734
George R Allan, 9075	04.2-060 Cabling, Raceways & Bus Ducts - Addition 3	Replace [04.2-060 Cabling, Raceways & Bus Ducts - Addition 3]	2013	\$71,723
George R Allan, 9075	04.3-020 Exterior Lighting - Original Building	Replace [04.3-020 Exterior Lighting - Original Building]	2013	\$7,339
George R Allan, 9075	04.5-050 Security System - Original Building	Replace [04.5-050 Security System - Original Building]	2013	\$7,288
George R Allan, Campus ID 9075 - Site	00.1-016 Soft Landscaping - Site	Replace [00.1-016 Soft Landscaping - Site]	2014	\$9,249
George R Allan, 9075	01.5-050 Interior Doors - Addition 2	Replace [01.5-050 Interior Doors - Addition 3]	2014	\$33,033
George R Allan, 9075	01.5-060C01 Paint Wallcovering	Replace [01.5-060C01 Paint Wallcovering - Addition 1]	2014	\$39,640
George R Allan, 9075	01.5-070C07 Hardwood - Original Building	Replace [01.5-070C07 Hardwood - Original Building]	2014	\$52,853
George R Allan, 9075	03.1-160 Central Station AHU - Original Building - basement	Replace [03.1-160 Central Station AHU - Original Building - basement]	2014	\$130,203
George R Allan, 9075	03.3-030 Domestic Water Heaters - Original Building	Replace [03.3-030 Domestic Water Heaters - Original Building]	2014	\$7,288
George R Allan, 9075	04.5-010 Fire Alarm System - Original Building	Replace [04.5-010 Fire Alarm System - Original Building]	2014	\$33,526
George R Allan, Campus ID 9075 - Site	00.3-013 Unpaved Sports & Recreational Spaces	Replace Unpaved Sports & Recreational Spaces	2015	\$13,213
George R Allan, 9075	04.7 Information Technology Systems - Original Building	Replace [04.7 Information Technology Systems - Original Building]	2017	\$10,689
George R Allan, 9075	01.5-055 Interior Door Hardware - Original Building	Replace Interior Door Hardware - Original Building	2018	\$15,856
George R Allan, 9075	01.5-090 Window Coverings - Original Building	Replace [01.5-090 Window Coverings - Original Building]	2018	\$66,066
George R Allan, 9075	04.3-010 Interior Lighting - Addition 4	Replace [04.3-010 Interior Lighting - Addition 4]	2018	\$83,448
George R Allan, 9075	03.1-160 Central Station AHU - Original Building - basement	Replace [03.1-160 Central Station AHU - Original Building - basement]	2019	\$130,203
George R Allan, 9075	04.3-030 Exit Lighting - Original Building	Replace [04.3-030 Exit Lighting - Original Building]	2019	\$6,900
			<b>Total</b>	<b>\$4,847,054</b>

School	Technical Category	Capital Renewal Description	Projected Implementation Year	Estimated Cost
Prince Philip, 9127	01.5-090 Window Coverings	Replace window coverings	2010	\$13,213
Prince Philip, 9127	01.3-010 Exterior Walls - Original Building	Replace [01.3-010 Exterior Walls - Original Building]	2010	\$13,213
Prince Philip, 9127	01.3-040 Windows - Original Building	Replace [01.3-040 Windows - Original Building]	2010	\$211,411
Prince Philip, 9127	01.4 Roofing - Original Building	Replace [01.4 Roofing - Original Building] Sections 104, 106, 301	2010	\$199,214
Prince Philip, 9127	01.5-020 Millwork - Original Building	Replace [01.5-020 Millwork - Original Building]	2010	\$158,558
Prince Philip, 9127	01.5-050 Interior Doors - Original Building	Replace [01.5-050 Interior Doors - Original Building]	2010	\$39,640
Prince Philip, 9127	01.5-055 Interior Door Hardware - Original Building	Replace [01.5-055 Interior Door Hardware - Original Building]	2010	\$19,820
Prince Philip, 9127	01.5-060C01 Paint Wallcovering - Original Building	Replace [01.5-060C01 Paint Wallcovering - Original Building]	2010	\$52,853
Prince Philip, 9127	01.5-060C04 Ceramic Wall Tile - Original Building	Replace [01.5-060C04 Ceramic Wall Tile - Original Building]	2010	\$10,571
Prince Philip, 9127	01.5-070C01 Ceramic Floor Tile - Original Building	Replace [01.5-070C01 Ceramic Floor Tile - Original Building]	2010	\$21,413
Prince Philip, 9127	01.5-070C04 Carpeting - Original Building	Replace [01.5-070C04 Carpeting - Original Building]	2010	\$19,820
Prince Philip, 9127	01.5-070C05 Vinyl Floor Tile - Original Building	Replace [01.5-070C05 Vinyl Floor Tile - Original Building]	2010	\$33,033
Prince Philip, 9127	01.5-070C06 Sheet Vinyl Floor - Original Building	Replace [01.5-070C06 Sheet Vinyl Floor - Original Building]	2010	\$19,437
Prince Philip, 9127	01.5-070C07 Hardwood - Original Building	Replace [01.5-070C07 Hardwood - Original Building]	2010	\$26,426
Prince Philip, 9127	01.5-080C05 Painted Ceiling Structures - Original Building	Replace [01.5-080C05 Painted Ceiling Structures - Original Building]	2010	\$7,928
Prince Philip, 9127	01.5-080C07 Acoustic Tile Ceiling - Original Building	Replace [01.5-080C07 Acoustic Tile Ceiling - Original Building]	2010	\$79,279
Prince Philip, 9127	01.5-090 Window Coverings - Original Building	Replace [01.5-090 Window Coverings - Original Building]	2010	\$35,043
Prince Philip, 9127	01.5-100 Washroom Accessories - Original Building	Replace [01.5-100 Washroom Accessories - Original Building]	2010	\$15,856
Prince Philip, 9127	01.5-110 Interior Stairs - Original Building	Replace [01.5-110 Interior Stairs - Original Building]	2010	\$21,164
Prince Philip, 9127	01.6 Fittings & Equipment - Original Building	Replace [01.6 Fittings & Equipment - Original Building]	2010	\$79,279
Prince Philip, 9127	03.1-010 (HW/S) Boilers - Original Building	Replace [03.1-010 (HW/S) Boilers - Original Building]	2010	\$92,492
Prince Philip, 9127	03.1-170 Heating & Cooling Piping Systems - Original Building	Replace [03.1-170 Heating & Cooling Piping Systems - Original Building]	2010	\$244,444
Prince Philip, 9127	03.1-180 HVAC Pumps - Original Building	Replace [03.1-180 HVAC Pumps - Original Building]	2010	\$7,928
Prince Philip, 9127	03.1-190 Terminal Units - Original Building	Replace [03.1-190 Terminal Units - Original Building]	2010	\$105,706
Prince Philip, 9127	03.1-250 Ventilation Fans - Original Building	Replace [03.1-250 Ventilation Fans - Original Building]	2010	\$19,820
Prince Philip, 9127	03.1-260 Stacks & Breaching - Original Building	Replace [03.1-260 Stacks & Breaching - Original Building]	2010	\$19,511
Prince Philip, 9127	03.2 Control Systems - Original Building	Replace [03.2 Control Systems - Original Building]	2010	\$66,066
Prince Philip, 9127	03.3-010 Plumbing Fixtures - Original Building	Replace [03.3-010 Plumbing Fixtures - Original Building]	2010	\$105,706
Prince Philip, 9127	03.3-050 Plumbing Piping Systems - Original Building	Replace [03.3-050 Plumbing Piping Systems - Original Building]	2010	\$158,558
Prince Philip, 9127	04.1-010 Primary Switchgear - Original Building	Replace [04.1-010 Primary Switchgear - Original Building]	2010	\$27,601
Prince Philip, 9127	04.2-010 Secondary Switchgear - Original Building	Replace [04.2-010 Secondary Switchgear - Original Building]	2010	\$39,640
Prince Philip, 9127	04.2-060 Cabling, Raceways & Bus Ducts - Addition 1	Replace [04.2-060 Cabling, Raceways & Bus Ducts - Addition 1]	2010	\$98,054
Prince Philip, 9127	04.3-010 Interior Lighting - Original Building	Replace [04.3-010 Interior Lighting - Original Building]	2010	\$105,706
Prince Philip, 9127	04.3-030 Exit Lighting - Original Building	Replace [04.3-030 Exit Lighting - Original Building]	2010	\$7,537
Prince Philip, 9127	04.3-040 Emergency Lighting - Addition 1	Replace [04.3-040 Emergency Lighting - Addition 1]	2010	\$8,451
Prince Philip, 9127	04.3-040 Emergency Lighting - Original Building	Replace [04.3-040 Emergency Lighting - Original Building]	2010	\$31,029
Prince Philip, 9127	04.5-010 Fire Alarm System - Original Building	Replace [04.5-010 Fire Alarm System - Original Building]	2010	\$52,853
Prince Philip, 9127	04.5-040 Communication Systems - Original Building	Replace [04.5-040 Communication Systems - Original Building]	2010	\$30,075
Prince Philip, 9127	03.3-050 Plumbing Piping Systems - Original Building	Study - Plumbing Piping Systems	2010	\$6,607
Prince Philip, 9127	03.1-170 Heating & Cooling Piping Systems - Original Building	Study - Heating & Cooling Piping Systems	2010	\$6,607
Prince Philip, 9127	01.4 Roofing Addition 2	Replace [01.4 Roofing - Addition 2] Section 202	2010	\$67,011
Prince Philip, Campus ID 9127 - Site	00.3-010 Unpaved Parking Lots	Replace paved parking lot	2010	\$33,033
Prince Philip, Campus ID 9127 - Site	00.2-014 Paved Walkways	Replace paved walkway	2010	\$26,426
Prince Philip, Campus ID 9127 - Site	00.2-011 Paved Roadway	Replace paved roadway	2010	\$39,640
Prince Philip, Campus ID 9127 - Site	00.1-014 Site Related Stairs, Plazas & Decks	Replace site related stairs	2010	\$33,033
Prince Philip, Campus ID 9127 - Site	00.1-010 Underground Utilities - Site	Replace [00.1-010 Underground Utilities - Site]	2010	\$66,066
Prince Philip, Campus ID 9127 - Site	00.2-012 Paved Playgrounds - Site	Replace [00.2-012 Paved Playgrounds - Site]	2010	\$46,246
Prince Philip, Campus ID 9127 - Site	00.1-010 Underground Utilities - Site	Replace [00.1-010 Underground Utilities - Site]	2010	\$6,607
Prince Philip, 9127	03.1-200 Gas Piping System - Original Building	Replace [03.1-200 Gas Piping System - Original Building]	2011	\$19,855
Prince Philip, 9127	03.3-030 Domestic Water Heaters - Original Building	Replace [03.3-030 Domestic Water Heaters - Original Building]	2011	\$3,879
Prince Philip, 9127	03.3-030 Domestic Water Heaters - Original Building	Replace [03.3-030 Domestic Water Heaters - Original Building]	2011	\$3,879

ReCAPP Event Listing: 2003 - 2021

May 6, 2011

Prince Philip, 9127	01.5-060C08 Glazed Wall Coatings - Original Building	Replace [01.5-060C08 Glazed Wall Coatings - Original Building]	2012	\$17,889
Prince Philip, 9127	04.3-020 Exterior Lighting - Original Building	Replace [04.3-020 Exterior Lighting - Original Building]	2012	\$10,847
Prince Philip, 9127	04.6-010 Clock Systems - Original Building	Replace [04.6-010 Clock Systems - Original Building]	2012	\$17,583
Prince Philip, 9127	01.5-060C01 Paint Wallcovering - Addition 1	Replace [01.5-060C01 Paint Wallcovering - Addition 1]	2013	\$17,910
Prince Philip, 9127	01.5-060C01 Paint Wallcovering - Original Building	Replace [01.5-060C01 Paint Wallcovering - Original Building]	2013	\$63,719
Prince Philip, 9127	01.5-060C08 Glazed Wall Coatings - Addition 1	Replace [01.5-060C08 Glazed Wall Coatings - Addition 1]	2013	\$10,057
Prince Philip, 9127	01.5-060C08 Glazed Wall Coatings - Original Building	Replace [01.5-060C08 Glazed Wall Coatings - Original Building]	2013	\$17,889
Prince Philip, 9127	01.5-070C04 Carpeting - Original Building	Replace [01.5-070C04 Carpeting - Original Building]	2013	\$20,956
Prince Philip, 9127	04.5-050 Security System - Original Building	Replace [04.5-050 Security System - Original Building]	2013	\$7,757
Prince Philip, 9127	01.4 Roofing - Addition 1	Replace [01.4 Roofing - Addition 1]	2016	\$143,009
Prince Philip, 9127	01.3-030 Exterior Doors - Original Building	Replace [01.3-030 Exterior Doors - Original Building]	2017	\$10,922
Prince Philip, 9127	01.5-055 Interior Door Hardware - Original Building	Replace [01.5-055 Interior Door Hardware - Original Building]	2018	\$21,608
Prince Philip, 9127	01.5-080C05 Painted Ceiling Structures - Original Building	Replace [01.5-080C05 Painted Ceiling Structures - Original Building]	2018	\$7,255
Prince Philip, 9127	01.5-100 Washroom Accessories - Original Building	Replace [01.5-100 Washroom Accessories - Original Building]	2018	\$19,094
Prince Philip, 9127	03.2 Control Systems - Original Building	Replace [03.2 Control Systems - Original Building]	2018	\$140,697
Prince Philip, 9127	04.3-020 Exterior Lighting - Addition 1	Replace [04.3-020 Exterior Lighting - Addition 1]	2018	\$7,802
Prince Philip, 9127	04.3-020 Exterior Lighting - Original Building	Replace [04.3-020 Exterior Lighting - Original Building]	2018	\$10,847
Prince Philip, 9127	03.3-030 Domestic Water Heaters - Original Building	Replace [03.3-030 Domestic Water Heaters - Original Building]	2021	\$3,879
Prince Philip, 9127	03.3-030 Domestic Water Heaters - Original Building	Replace [03.3-030 Domestic Water Heaters - Original Building]	2021	\$3,879
			<b>Total</b>	<b>\$3,210,836</b>