

Asset	Technical	Brief Description	Event Year	Event Cost	Baseline Priority
Westmount SS, Campus ID 9159 - Site	00.2-010 Paved Parking Lots - Site	Replace [00.2-010 Paved Parking Lots - Site]	2010	\$422,822	High
Westmount SS, Campus ID 9159 - Site	00.2-014 Paved Walkways - Site	Replace [00.2-014 Paved Walkways - Site]	2010	\$79,279	High
Westmount SS, Campus ID 9159	01.3-010 Exterior Walls - Original Building	Repair [01.3-010 Exterior Walls - Original Building]	2010	\$112,312	High
Westmount SS, Campus ID 9159	01.4 Roofing - Original Building - Section 101	Replace [01.4 Roofing - Original Building - Section 101]	2010	\$79,279	High
Westmount SS, Campus ID 9159	01.5-110 Interior Stairs	Replace [01.5-110 Interior Stairs] - damaged/missing handrail covers	2010	\$6,607	High
Westmount SS, Campus ID 9159	03.1-010 (HW/S) Boilers - Original Building	Replace [03.1-010 (HW/S) Boilers - Original Building]Replace existing gas-fired hot water heating Boiler #1 - Original B	2010	\$66,066	High
Westmount SS, Campus ID 9159	03.1-010 (HW/S) Boilers - Original Building	Replace [03.1-010 (HW) Boilers - Original Building]Replace gas-fired hot water heating Boiler #2 - Original Building	2010	\$66,066	High
Westmount SS, Campus ID 9159	03.1-030 (HW/S) Boiler Auxiliary System	Replace [03.1-030 (HW/S) Boiler Auxiliary System]Replace Boiler Auxiliary Systems are part of the boiler replacement	2010	\$39,640	High
Westmount SS, Campus ID 9159	03.1-160 Central Station AHU	Replace [03.1-160 Central Station AHU]Replace Central Station AHUs 1-4	2010	\$158,558	High
Westmount SS, Campus ID 9159	03.1-180 HVAC Pumps - Original Building	Replace [03.1-180 HVAC Pumps - Original Building]Replace existing HW Heating Pumps: P1, P2 and P3.	2010	\$52,853	High
Westmount SS, Campus ID 9159	03.1-190 Terminal Units - Addition 1	Replace [03.1-190 Terminal Units - Addition 1]Replace existing terminal units in Addition 1.	2010	\$72,673	High
Westmount SS, Campus ID 9159	03.1-190 Terminal Units - Original Building	Replace [03.1-190 Terminal Units - Original Building]Replace existing terminal units in the Original Building.	2010	\$132,132	High
Westmount SS, Campus ID 9159	03.1-260 Stacks & Breaching - Original Building	Replace [03.1-260 Stacks & Breaching - Original Building]Replace the boiler stacks and breaching during the boiler rep	2010	\$33,033	High
Westmount SS, Campus ID 9159	03.3-010 Plumbing Fixtures	Replace [03.3-010 Plumbing Fixtures]Replace existing Plumbing Fixtures including: lavatories, drinking fountains, Brad	2010	\$66,066	High
Westmount SS, Campus ID 9159	03.3-040 Plumbing Pumps - Original Building	Replace [03.3-040 Plumbing Pumps - Original Building]Replace sump pit pump.	2010	\$6,607	High
Westmount SS, Campus ID 9159	03.4-090 Vehicle Fuel Storage and Distribution	Replace [03.4-090 Vehicle Fuel Storage and Distribution]Replace above ground fuel storage tank.	2010	\$19,820	High
Westmount SS, Campus ID 9159	04.2-010 Secondary Switchgear	Replace [04.2-010 Secondary Switchgear]Replace existing Secondary Switchgear.	2010	\$105,706	Urgent
Westmount SS, Campus ID 9159	04.5-030 Emergency Power System	[04.5-030 Emergency Power System]Connect the emergency power circuit in the original building to the gas generator	2010	\$66,066	Urgent

Asset	Technical	Brief Description	Event Year	Event Cost	Baseline Priority
Barton, 9066	01.3-040 Windows - Addition 1	Replace single glazed fixed glass window at the technology shop building facade.	2010	\$26,426	High
Barton, 9066	04.2-060 Cabling, Raceways & Bus Ducts	Replace the "Cable, Raceways & Bus-ducts" systems based on the study findings	2010	\$264,264	High
Barton, 9066	03.3-050 Plumbing Piping Systems	Replace the plumbing piping system based on the study findings	2010	\$330,330	High
Barton, 9066	03.1-190 Terminal Units	Replace terminal units	2010	\$607,807	High
Barton, 9066	03.1-170 Heating & Cooling Piping Systems	Replace heating piping based on the study findings	2010	\$330,330	High
Barton, 9066	04.2-060 Cabling, Raceways & Bus Ducts	Study - Condition of electrical distribution equipment.	2010	\$6,607	High
Barton, 9066	03.3-050 Plumbing Piping Systems	Study - Condition of the plumbing piping system	2010	\$6,607	High
Barton, Campus ID 9066 - Site	00.1-014 Site Related Stairs, Plazas & Decks - Site	Restore all deteriorated exterior stairs.	2010	\$26,426	High

Asset	Technical	Brief Description	Event Year	Event Cost	Baseline Priority
Hill Park, 9086	04.3-020 Exterior Lighting	Replace the exterior lighting.	2010	\$66,066	High
Hill Park, 9086	03.3-050 Plumbing Piping Systems	Replace the plumbing piping systems.	2010	\$330,330	High
Hill Park, 9086	03.3-010 Plumbing Fixtures	Replace the plumbing fixtures in eight washrooms and ten Bradley basins in technology shops.	2010	\$290,690	High
Hill Park, 9086	03.1-190 Terminal Units	Replace the terminal units.	2010	\$330,330	High
Hill Park, 9086	04.2-060 Cabling, Raceways & Bus Ducts	Replacethe cabling, raceways & bus ducts.☐	2010	\$330,330	High
Hill Park, 9086	04.5-040 Communication Systems - Original Building	Replace communication system, speakers and two-way communication devices.	2010	\$59,459	High
Hill Park, 9086	03.1-250 Ventilation Fans - Original Building	Replace eight exhaust fans including the kitchen exhaust fan.	2010	\$13,213	High
Hill Park, 9086	03.1-200 Gas Piping System - Original Building	Replace the gas piping system.	2010	\$66,066	High
Hill Park, 9086	01.3-040 Windows - Original Building	Replace [01.3-040 Windows - Original Building] Replace all windows in the original building. Windows at the corrid	2010	\$660,660	High
Hill Park, 9086	03.1-180 HVAC Pumps - Original Building	Replace ten hot water circulation pumps.	2010	\$19,820	High
Hill Park, 9086	04.5-010 Fire Alarm System - Original Building	Replace the fire alarm system(Field units only).	2010	\$66,066	High
Hill Park, 9086	04.2-060 Cabling, Raceways & Bus Ducts	Study the cabling, raceways & bus ducts.	2010	\$6,607	High
Hill Park, 9086	03.3-050 Plumbing Piping Systems	Study the plumbing piping systems.	2010	\$6,607	High
Hill Park, Campus ID 9086 - Site	00.1-014 Site Related Stairs, Plazas & Decks - Site	Replace [00.1-014 Site Related Stairs, Plazas & Decks - Site] External stairway leading to the basement	2010	\$33,033	High

Asset	Technical	Brief Description	Event Year	Event Cost	Baseline Priority
Mountain Secondary, 9101	03.3-030 Domestic Water Heaters	Replace one indirectly heated domestic water storage tank.	2010	\$39,640	High
Mountain Secondary, 9101	03.1-130 Window Unit A/C - Cool	Replace 6 of the 12 window type A/C units.	2010	\$3,964	High
Mountain Secondary, 9101	03.1-030 (HW/S) Boiler Auxiliary System	Replace the boiler auxiliary system.	2010	\$33,033	High
Mountain Secondary, 9101	01.3-040 Windows - Original Building	Replace [01.3-040 Windows - Original Building]	2010	\$330,330	High
Mountain Secondary, 9101	01.4 Roofing - Original Building	Replace [01.4 Roofing - Original Building] of roof except the Gymnasium roof - Sections 101, 102, 103	2010	\$776,953	High
Mountain Secondary, 9101	03.1-010 (HW/S) Boilers - Original Building	Replace one hot water fire tube boiler.	2010	\$105,706	High
Mountain Secondary, 9101	03.1-160 Central Station AHU - Original Building	Replace two central station AHUs.(Heating only).	2010	\$79,279	High
Mountain Secondary, 9101	03.1-180 HVAC Pumps - Original Building	Replace eight hot water circulation pumps.	2010	\$13,213	High
Mountain Secondary, 9101	03.1-250 Ventilation Fans - Original Building	Replace approximately forty rooftop exhaust fans.	2010	\$66,066	High
Mountain Secondary, 9101	03.1-260 Stacks & Breaching - Original Building	Replace the stack and breaching for the boiler.	2010	\$13,213	High
Mountain Secondary, 9101	03.2 Control Systems - Original Building	Replace pneumatic control system.	2010	\$79,279	High
Mountain Secondary, 9101	03.3-050 Plumbing Piping Systems - Original Building	Replace the plumbing piping systems.	2010	\$158,558	High
Mountain Secondary, 9101	04.5-010 Fire Alarm System - Original Building	Replace the fire alarm system.	2010	\$66,066	High
Mountain Secondary, 9101	04.5-040 Communication Systems - Original Building	Replace the total communication system.	2010	\$52,853	High
Mountain Secondary, 9101	03.3-050 Plumbing Piping Systems - Original Building	Study the plumbing piping systems.	2010	\$6,607	High

Asset	Technical	Brief Description	Event Year	Event Cost	Baseline Priority
Sherwood SS, 9143	04.5-040 Communication Systems	Repair the public address system	2010	\$59,459	High
Sherwood SS, 9143	04.6-030 Electrical Heating Systems	Replace or upgrade the electrical heating systems	2010	\$26,426	High
Sherwood SS, 9143	04.2-010 Secondary Switchgear	Replace the secondary switchgear based on the study findings	2010	\$475,675	Urgent
Sherwood SS, 9143	03.3-050 Plumbing Piping Systems	Replace the plumbing piping system based on the study findings	2010	\$330,330	High
Sherwood SS, 9143	03.2 Control Systems	Replace control components	2010	\$132,132	High
Sherwood SS, 9143	03.1-250 Ventilation Fans	Replace ventilation fans (25%)	2010	\$46,246	High
Sherwood SS, 9143	03.1-190 Terminal Units	Replace terminal unit	2010	\$369,970	High
Sherwood SS, 9143	03.1-180 HVAC Pumps	Replace HVAC pumps	2010	\$52,853	High
Sherwood SS, 9143	03.1-160 Central Station AHU	Replace central station AHU (3) - Gymnasium units	2010	\$158,558	High
Sherwood SS, 9143	03.1-160 Central Station AHU	Replace central station AHUs' components	2010	\$59,459	High
Sherwood SS, 9143	04.2-060 Cabling, Raceways & Bus Ducts	Replace the "Cable, Raceways & Bus-ducts" systems based on the study findings	2010	\$594,594	High
Sherwood SS, 9143	04.2-060 Cabling, Raceways & Bus Ducts	Study - Condition of Cabling, Raceways & Bus Ducts	2010	\$10,571	High
Sherwood SS, 9143	04.2-010 Secondary Switchgear	Study - Condition and service capacity of secondary switchgear	2010	\$10,571	Urgent
Sherwood SS, 9143	03.3-050 Plumbing Piping Systems	Study - Condition of plumbing piping systems	2010	\$6,607	High
Sherwood SS, Campus ID 9143 - Site	00.1-014 Site Related Stairs, Plazas & Decks - Site	Replace all exterior stair assemblies.	2010	\$66,066	High

Asset	Technical	Brief Description	Event Year	Event Cost	Baseline Priority
Sir Allan MacNab SS, 9145	01.3-040 Windows - Original Building	Replace windows based on age and condition.	2010	\$726,726	High
Sir Allan MacNab SS, 9145	03.1-200 Gas Piping System - Original Building	Replace the gas piping system, based on observed conditions.	2010	\$52,853	High
Sir Allan MacNab SS, 9145	03.1-250 Ventilation Fans - Original Building	Replace the roof-top ventilation fans based on observed conditions. There are approximately thirty units.	2010	\$39,640	High
Sir Allan MacNab SS, 9145	03.3-040 Plumbing Pumps - Original Building	Replace the plumbing pumps, based on indicated and observed conditions.	2010	\$19,820	High
Sir Allan MacNab SS, 9145	03.3-050 Plumbing Piping Systems - Original Building	Replace the plumbing piping systems, including the primary, secondary and sanitary lines; based on the findin	2010	\$224,624	High
Sir Allan MacNab SS, 9145	04.3-030 Exit Lighting - Original Building	Replace the exit lighting, based on observed conditions.	2010	\$19,820	High
Sir Allan MacNab SS, 9145	03.3-050 Plumbing Piping Systems - Original Building	Study to determine the condition of the plumbing piping system, including the primary, secondary and sanitary	2010	\$6,607	High