

SCHOOL: BENNETTO - 47 SIMCOE ST E, HAMILTON

JOB: TMR-1749-01

| UNIT TYPE AND TAG | MODEL | SERIAL | UNIT LOCATION | BELT | FILTER | SERVES | TIME TO COMPLETE CHECK (MINUTE) | REQUIRES IMMEDIATE ATTENTION | NOTES |
|-------------------|--------------------|---------------|-------------------------|--------------|-------------|--------|---------------------------------|---|----------------------------|
| R227 | CAH1000 PA VP D | 7066 0221 H | Air Ventilator Room 227 | Direct Drive | Washable | | | No power at unit | |
| R229 | CAH1000 PA VP D | 7018 0171 H | Air Ventilator Room 229 | Direct Drive | Washable | | | No power at unit | |
| R224 | CAH1000 PA VP D | 7067 0221 H | Air Ventilator Room 224 | Direct Drive | Washable | | | | |
| R232 | CAH1000 PA VP D | 7017 0171 H | Air Ventilator Room 232 | Direct Drive | Washable | | | | |
| MARK1 | GB-180-5-X | 12801193 1203 | | AP25 | | | | No belt on site | |
| EF10 | GB-240-10-X | 12167859 1007 | | A35 | | | | | |
| Carrier RTU | 48HCFD14A3A1A0A0G0 | 3819P03358 | | BX67 | (6) 18x24x2 | | | | |
| CARRIER RTU | 48TJF028--181BA | 2902F66611 | | B47 | (2)20X20X2 | | | | |
| HRV | 1401C-4145-3RDS | | | BX54 | (4)16X25X2 | | | | |
| EF8 | G-131-VG-X | 12167614 1007 | | Direct Drive | | | | | |
| EF11 | G-080-VG-X | 12167617 1007 | | Direct Drive | | | | No power at unit | |
| EF14 | G-080-VG-X | 12167619 1007 | | Direct Drive | | | | No power at unit | |
| RTU | 48HCFD17A7A1-56450 | 3819P24515 | | BX48 | (6)20X25X2 | | | | |
| EF3 | G-131-VG-X | 12167612 1007 | | Direct Drive | | | | | |
| EF4 | G-131-VG-X | 12167610 1007 | | Direct Drive | | | | No power at unit | |
| EF1 | G-131-VG-X | 12167613 1007 | | Direct Drive | | | | No power at unit | |
| RTU | 48TFE012-M-111 | 1702G50471 | | bx47 | (4)20x20x2 | | | Found no low voltage unit not running | Compressor contactor burnt |
| HRV | 1401B-1620-1RD9 | | | BX33 BX36 | (4) 16X20X2 | | | Unable to test unit due to power issues on rtu. | |