

Chedoke Elementary School
500 Bendamere Avenue
Hamilton, ON
L9C 1R3

September 11th, 2020

Dear Mr. Sokolowski,

VCI CONTROLS has conducted a preliminary check of the HVAC systems at the above-mentioned location. At the time of inspection, and at the completion of the repairs all of the HVAC systems were functioning at manufactures specifications.

Exhaust fan #2 which feeds room # 126A has a defective fan motor and has been order will return when motor has arrived. Lead time is approx. 1-2 weeks

Roof top unit requires enthalpy board which is not impacting ventilation air being served by the equipment. Lead time on enthalpy board is approx. 1 week

Regards,

Jeffrey Morneau

National Service Manager
VCI CONTROLS INC.