

Franklin Road School  
500 Franklin Road  
Hamilton, ON  
L8V 2A4

September 11<sup>th</sup>, 2020

Dear Mr. Sokolowski,

VCI CONTROLS has conducted a preliminary check of the HVAC systems at the above-mentioned location. At the time of inspection, and at the completion of the repairs all of the HVAC systems were functioning at manufactures specifications.

No additional work is required

Regards,

Jeffrey Morneau

National Service Manager  
VCI CONTROLS INC.