

GLENWOOD SCHOOL

Equipment	Model/Serial	Location	What it Serves	Time Spent	Filters	Belts	Repairs Needed or Repaired
AHU 1	EngAir FWA173-DJE4010 / B41040 AHU1			45 min	(4of) 20x24x2	(1of) B65 (1of) A59	Adjusted belt tension / Filters need to be replaced none on site - Completed
AHU 2	EngAir FWA173-DJE4010 / B41049 AHU2			45 min	(4of) 20x24x2	(1of) A61 (1of) A53	Replaced Belt and tightened / Filters need to be replaced / Evap coil fins damaged but no signs of coil leaking - Completed
EF	Greenheck GB091-4-X / 06H12043			20 min		(1of) 3L200	Belt needs to be replaced - adjusted tension - Completed
EF	Greenheck GB091-4-X / 06H12044			20 min		(1of) 3L200	Belt needs to be replaced - completed
EF	Greenheck GB091-4-X / 06H12045			20 min		(1of) 3L210	Belt needs to be replaced - completed
EF	Greenheck GB091-4-X / 06H12046			20 min		(1of) 3L210	Belt needs to be replaced - adjusted tension - Completed
EF	Greenheck GB091-4-X / 06H12030			20 min		(1of) 3L210	
EF	Greenheck GB091-4-X / 06H12047			20 min		(1of) 3L210	Belt needs to be replaced - completed
RTU 1	Lennox LGA090H4BH3Y / 5606J14487			45 min	(4of) 18x24x2	(1of) A46	Replaced belt
Fan Coil	Delhi 207 / NA			30 min	(1of) 25x25x1 Media	(1of) 4L320	Replaced belt
Fan Coil	Delhi 207 / NA			30 min	(1of) 20x25x1 Media	(1of) 4L320	
Fan Coil	Delhi 207 / NA			30 min	(1of) 25x25x1 Media	(1of) 4L320	

Administrative 20 min