

Park

Unit Type and Tag	Model	Serial Number	Unit Location	Serves	Complete Check	Immediate	Materials	Comments
UV1 eng air	RUV1200	Q1748UV1	rm 111	rm 111	30	Y	1-20X24X2 pltd	need to clean heating coil
UV2 eng air	RUV1200	Q1748UV2	rm 112	rm112	30	Y	1-20X24X2 pltd	need to clean heating coil
UV3 eng air	RUV1200	Q1748UV3	rm 113	rm 113	30	Y	1-20X24X2 pltd	need to clean heating coil
UV change air	CAH1200PARCD	321501031	rm 103	rm 103	30	N	2-16X16X1 pltd	found switch off inside turned on
UV change air	CAE1000PAVPD	320100431	P206	P206	30	N	2-16X16X1 pltd	
UV change air	CAE1000PAVPD	319900431	P207	P207	30	N	2-16X16X1 pltd	
UV change air	CAE1000PAVPD	320300431	P208	P208	30	N	2-16X16X1 pltd	
UV change air	CAE1000PAVPD	319800431	P16	P16	30	N	2-16X16X1 pltd	
UV change air	CAE1000PAVPD	320000431	P15	P15	30	N	2-16X16X1 pltd	
UV change air	CAE1000PAVPD	320200431	P14	P14	30	N	2-16X16X1 pltd	
RTU	Carrier	3403G10141	roof	Gym west	45	Y	1-A402-16X25X2 pltd	clean evap coils and econo filter
RTU	Carrier	3403G10140	roof	Gym east	45	Y	1-A402-16X25X2 pltd	clean evap coils and econo filter
EF	dome		roof	Gym	15	Y	1-4L280	needs belt not running
EF greenheck	G123CX		roof south east	east	15	N		
EF greenheck	G143CX		roof south east	east	15	Y	not operating	
EF greenheck	G150BX		roof south east	east	15	Y	not operating	
EF greenheck	G123BX		roof south east	east	15	Y	not operating	
DMS	Carrier		roof centre	staff rm	15	N	washable	removed and cleaned filters
EF	dome		roof centre	centre	15	Y	1-4L260	belt broken and not optg
EF greenheck	G150BX		roof centre	centre	15	Y		not operating
EF greenheck	G150BX		roof centre	centre	15	Y		not operating
EF greenheck	G150BX		roof centre	centre	15	Y		not operating
EF greenheck	G150BX		west roof	west	15	Y		not operating
EF greenheck	G150BX		west roof	west	15	Y		not operating
EF greenheck	G150BX		west roof	west	15	Y		not operating
EF	dome		west roof	west	15	Y	1-4L260	needs belt not optg