

2.5 HRS.

HWDSB	SCHOOL:	Mary Hopkins Elementary School				
Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.)	Model	Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.)	Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.)	Time To Complete Check (minutes)	Requires Immediate Attention to maintain ventilation	Comments
E.F	Dome Fan	1st floor Roof	West Foyer (Beside Gym)	15/30/45	Y/N	- Unit excessive vibration - noisy. - working.
E.F	Xpelair	Boys Washroom	1st floor	15/30/45	Y/N	- Unit working
EF	Xeplair	Girls washroom	1st floor	15/30/45	Y/N	- Unit working
E.F	Woods Fan (Dome Fan)	main roof top floor	Library	15/30/45	Y/N	- Unit working
E.F.	Floaire BDCR 15" series	Kinder garten roof	Kindergarten	15/30/45	Y/N	- Unit not working.
E.F	Sheldon's Design #12	Day care wing roof	Hallway Room 215	15/30/45	Y/N	- Bearings overgreased. - Vibration. (very old unit)
E.F	Trane ^{centrifugal fan size 18}	Penthouse Kindergarten	Kindergarten Bathrooms	15/30/45	Y/N	- Not working.
E.F	Trane ^{centrifugal fan size 12}	Penthouse Kindergarten	Kindergarten Bathroom	15/30/45	Y/N	- needs belts → worn → A34 (4L360) - Not working
E.F	Xpelair	Room 208	Boys Bathroom	15/30/45	Y/N	- working unit
E.F	Xpelair	Room 207	Boys Bathroom	15/30/45	Y/N	- working unit
				15/30/45	Y/N	
				15/30/45	Y/N	
				15/30/45	Y/N	

HWDSB	SCHOOL:	Mill Grove school / Mary Hopkins school				
Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.)	Model	Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.)	Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.)	Time To Complete Check (minutes)	Requires Immediate Attention to maintain ventilation	Comments
RTU	ZXG14T2C3AB (Johnson Control)	Roof	class rooms	15/30/45	(Y/N)	- Air filters need replaced (20x20x2) 4 att. - economizer filters need cleaned - Air filters need replaced (12 total) - Fault display (using return instead of space Temp.)
RTU	J152JS40R2A Johnson Control (Fisen)	Roof	old school building	15/30/45	(Y/N)	Immediate action req'd
				15/30/45	Y/N	
	Mill Grove school			15/30/45	Y/N	
				15/30/45	Y/N	
	Mary Hopkins school			15/30/45	Y/N	
Univent	Ruv G 1600 Engineered Air	217 B	class room	15/30/45	Y/N	
Univent	Ruv G 1600 Engineered Air	217 A	classroom	15/30/45	Y/N	
RTU 1	Carrier 48TJD014	Gym Roof	Gym	15/30/45	(Y/N)	- Fan belt B46 5L490 - Need replaced - Filters and evaporator dirty.
RTU 2	Carrier 48TJD014	Gym Roof	Gym	15/30/45	Y/N	- Filters dirty - Louvre function not tested.
Exhaust Fan	DX-7B Penn Ventilator	Foyer roof	Foyer beside Gym	15/30/45	Y/N	- Fan out of balance - Shaking - need bearings replaced
A/C	Carrier	office	office	15/30/45	Y/N	
Furnace	Carrier weathermaker 9200	staff rm closet	staff Room	15/30/45	Y/N	

No filters found on sites.

3/15 Alan Tice

HWDSB	SCHOOL:	Mary Hopkins				
Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.)	Model	Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.)	Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.)	Time To Complete Check (minutes)	Requires Immediate Attention to maintain ventilation	Comments
	Earl Kitchener school			15/30/45	Y/N	
RTU	Lennox LGC180S2BM21	Roof	Rm. 021 Gym	15/30/45	Y/N	
A/C	America Series EMI	Window	Room 006	15/30/45	Y/N	Filter dirty.
A/C F.C	Lennox CB29M	Room 120B	office staff Rm	15/30/45	Y/N	
RTU		Roof	Tempered air Full building	15/30/45	Y/N	→ filters dirty need 11 → 18x25x2
				15/30/45	Y/N	
	Mary Hopkins School (cont'd)			15/30/45	Y/N	
				15/30/45	Y/N	
Unit ventilator	Series 1100 Change Air			15/30/45	Y/N	- cleaned filters
Unit ventilator	series 1000 Change Air			15/30/45	Y/N	- cleaned filters
Unit ventilator	sophomore series Change Air.			15/30/45	Y/N	- cleaned filters
				15/30/45	Y/N	
				15/30/45	Y/N	