

MEMORIAL SCHOOL

Equipment	Model/Serial	Location	What it Serves	Time Spent	Filters	Belts	Repairs Needed or Repaired
MUA 1	EngAir FWB304-DJE140-0 / B42603 MUA1			30 min			Replaced Belts with site stock / found VFD off on High amp fault adjusted belt and Tension working now - Coils dirty need to be power washed - Completed
Ductless	Daiken RXYMQ48PVJU / E006439	Daycare	Room 10/110	20 min			Room 110 curently down due to ongoing service due to lack of access
EF 1	Greenheck GB-091-4-X / 10949317-0707			15 min			
RTU	Carrier 24ABR330A510 / 0907E07453		Admin Room 105	30 min			
ERU	Carrier 24ABR324A320 / 2007E30185		Staff Room 153	30min			
Window A/C			Rooms 213 & 214	15 min			All tested and checked no issues
AH 1	Carrier 39LG1121AA1131-R / 3292T25721			20 min			No issues found
AH 2	Carrier 39LG1081AA1121-R / 3192T25722			20 min			No issues found
ERV 1	Cook 1500ERVH ERV-1500H / 403SE33700-00/0000701	Rear of school on ground	Annex	30 min			Replaced filters with site stock

Administrative 20 min