

HWDSB	SCHOOL:	Mill Grove Elementary School				
Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.)	Model	Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.)	Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.)	<del>replaced filters</del> Time To Complete Check (minutes)	Requires Immediate Attention to maintain ventilation	RTU Inspected last week - caretaker brought this to my attention Comments
RTU <del>RTU</del>	JISZJS40RZACA FISEN (replaced filters)	1A1 Roof	Gym, classrooms	15/30/45	Y/N	- Room 120 hatch ventilation blowing into room. (unit in fault)
wall unit		Rm 114 staff rm	staff room	15/30/45	Y/N	- checked unit operation
wall unit		staff Rm	staffroom	15/30/45	Y/N	- checked unit operation
wall unit		staff Rm	staff room.	15/30/45	Y/N	- checked unit operation.
Heat pump	Lennox	Room 106	west Rm 106	15/30/45	Y/N	- checked operation - o.k
Heat pump	Lennox	Room 107	west Rm 107	15/30/45	Y/N	- checked operation - o.k
Heat pump	Lennox	Room 108	west Rm 108	15/30/45	Y/N	- BAS Enabled - unit satisfied S.P. (must verify)
Heat pump	Lennox	Room 109	west side Rm 109	15/30/45	Y/N	- BAS Enabled - unit S.P - satisfied (must verify)
Heat pump	Lennox	Room 112	East side Rm 112	15/30/45	Y/N	- checked operation - o.k.
Heat pump	Lennox	Room 113	East side Rm 113	15/30/45	Y/N	- BAS Enabled - unit set point satisfied (must verify)
Heat pump	Lennox	Room 114	East side Rm 114	15/30/45	Y/N	- Bas Enabled - unit set point satisfied (must verify).
EF 01	Greencheck CW-095-V6-X	Rear wall	Boys Bathroom	15/30/45	Y/N	- unit not working
EF 02	Greencheck CW-095-V6-X	Rear wall	Girls Bathroom	15/30/45	Y/N	- working. O.K.

\* Please Note: checked heat pump unit operation through exhaust (Rooms occupied with teachers on zoom meetings)

HWDSB	SCHOOL:	Mill Grove school		<del>Mary Hopkins school</del>		
Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.)	Model	Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.)	Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.)	Time To Complete Check (minutes)	Requires Immediate Attention to maintain ventilation	Comments
RTU	ZxG14T2C3AB <del>          </del> (Johnson Control)	Roof	class rooms	15/30/45	Y/N	- Air filters need replaced (20x20x2) 4 att. - economizer filters need cleaned
RTU	J152JS40R2A Johnson Control (Fisen)	Roof	old school building	15/30/45	Y/N	- Air filters need replaced (12 total) - Fault display (using return instead of space Temp.)
				15/30/45	Y/N	[ Immediate action req'd ] ←
	Mill Grove school ↗			15/30/45	Y/N	
				15/30/45	Y/N	
	<del>Mary Hopkins school ↘</del>			<del>15/30/45</del>	<del>Y/N</del>	
<del>Univent</del>	<del>RuvG 1600 Engineered Air</del>	<del>217 B</del>	<del>class room</del>	<del>15/30/45</del>	<del>Y/N</del>	
<del>Univent</del>	<del>RuvG 1600 Engineered Air</del>	<del>217 A</del>	<del>classroom</del>	<del>15/30/45</del>	<del>Y/N</del>	
<del>RTU 1</del>	<del>Carrier 48TJD014</del>	<del>Gym roof</del>	<del>Gym</del>	<del>15/30/45</del>	<del>Y/N</del>	<del>- Fan belt B46 5L490 - need replaced - Filters and evaporator dirty.</del>
<del>RTU 2</del>	<del>Carrier 48TJD014</del>	<del>Gym roof</del>	<del>Gym</del>	<del>15/30/45</del>	<del>Y/N</del>	<del>- Filters dirty - Louvre function not tested.</del>
<del>Exhaust Fan</del>	<del>DX-7B Penn ventilator</del>	<del>Foyer roof</del>	<del>Foyer beside Gym</del>	<del>15/30/45</del>	<del>Y/N</del>	<del>- Fan out of balance - shaking - need bearings replaced</del>
<del>A/C</del>	<del>Carrier</del>	<del>office</del>	<del>office</del>	<del>15/30/45</del>	<del>Y/N</del>	
<del>Furnace</del>	<del>Carrier weather maker 9200</del>	<del>staff rm closet</del>	<del>staff room</del>	<del>15/30/45</del>	<del>Y/N</del>	

No filters found on sites.