

QUEENSDALE SCHOOL

Equipment	Model/Serial	Location	What it Serves	Time Spent	Filters	Belts	Repairs Needed or Repaired
AHU 1	EngAir LM8C / M13882-AHU1		Various Areas	45 min	(3of) 16x20x2 - Pleated (3of) 20x20x2 - Pleated	(1of) B72 (1of) B68	Needs new Belts - Bearings Greased - Completed
HRV-1	EngAir FWB313C0 / M13882 HRV1		Gym	45 min	(15of) 20x24x2 - Pleated (3of) 24x24x2 - Pleated	(2of) B85 (2of) BX85	Needs new Belts - Bearings Greased - Completed
RTU 1	EngAir FWA52CO / M13882 RTU 1		Main Offices	45 min	(1of) 24x24x2 - Pleated	(1of) A43 (1of) A35	Belts need to be replaced - Completed
RTU 2	EngAir FWEA62CO / M13882 RTU2			45 min	(1of) 12x24x2 - Pleated (1of) 24x24x2 - Pleated	(1of) A39	Needs new Belts - Bearings Greased - Completed
AHU	ChangeAir CAE1000APA VPD / 1804 1055F	Room 103		30 min	Washable		Electric Heat contactor needs replacing 2 pole 24v coil - Completed
AHU	Changeair CAE100A PA VPD / 1798 1055F	Room 104		30 min	Washable		
AHU	Changeair CAE1000A PA VPD / 1806 1045f	Room 102		30 min	Washable		Heating contactor pitted
AHU	Changeair CAE 1000A PA VPD / 1799 1055f	Room 101		30 min	Washable		
AHU	Changeair CAE 4036 PA ERWE / 1308 1118E	Room 107		30 min	(2of) 18x18x2 - Pleated		
RTU 1	Lennox LG060H4BH5J / 5606H1092	Lower Roof	Gym	30 min			Adjusted loose belt
RTU	Carrier 48HCEA04E2A1A0B0A0 / 3415C85242	NE Side Low Roof	NE Corridor Classroom	30 min			
RTU	Carrier 48HCEA04E2A1A0B0A0 / 3415C85241	NW Side Low Roof	NW Corridor Classroom	30 min			Inner Condenser coil dirty - needs to be cleaned - Completed
Exhaust Fan	Pennbarry L618219 / H18AA82962	NE Side Low Roof	N Corridor	15 min			
Exhaust Fan 4	Cook 120ACE120C5B / 0004391	N Side Low Roof Roof Middle	Classrooms Switch outside room 130	15 min			Motor seized, pulleys (Blower Pulley 3-1/x3/4 shaft fixed - Motor Pulley 3-3/4x1/2 adjustable Belt A20 20x20 Curb - Completed
Exhaust Fan 3	Cook 120ACE120C5B / 0003101	Northside Low Roof Middle	Classrooms Switch outside room 130	15 min			Motor bearings bad - mounting bracket broken - Completed
Exhaust Fan	Pennbarry L618219 / H18AB04137	North side Low Roof North	Classrooms	15 min			Blower shaft bearings noisy - Completed
RTU	Lennox LGA060H4BH5J / 5606H01093	High Roof	Gym North	30 min			Ptrap cracked, belt very loose adjusted needs new belt AX43 - Completed
Exhaust Fan 1	Cook 180CPV	Basement	General	15 min			Loose Belt adjusted
Exhaust Fan 2	Cook 135CP / 2201	Basement Mech RM	Sanitary Exh	15 min			Loose Belt adjusted
AHU	ChangeAir CAE1000PAVPD / 67000041G	Portable 1	Portable 1	30 min			Washable Filter plugged needs replacing (18-1/2x32-1/2) - Completed
AHU	ChangeAir EPA361000BC / 24010267C	Portable 3	Portable 3	30 min			Washable Filter plugged cleaned other missing - need 16x20 washable - Completed
AHU	ChangeAir EPA361000BC / 23870267C	Portable 2	Portable 2	30 min			Washable Filters plugged washed them

Administrative 30 min