

SALTFLEET SCHOOL

| Equipment | Model/Serial | Location | What it Serves | Time Spent | Filters | Belts | Repairs Needed or Repaired |
|---------------|--------------------------|--------------------------|----------------|------------|---------|-------|--|
| HRU 1 | EngAir FWA-224-C | Awing Mechanical Room | Multi | 45 min | | | Circuit 2 and 3 no charge R-22 - Completed |
| HRU 2 | EngAir FWA-224-C | Bwing Mechanical Room | Multi | 45 min | | | |
| HRU 3 | EngAir FWC93/DJX40-0 | New Section | | 45 min | | | Broken 1-1/2" Drain Trap - Completed |
| AHU 1 | Trane K5L90404 | Bwing Mechanical Room | Multi | 45 min | | | |
| Tower | BAC F1443-PCR | Awing Mechanical Room | Multi | 45 min | | | |
| AHU 3 | ChangeAir 95-013-294 | Portable 3 | Portable 3 | 30 min | | | |
| AHU 4 | ChangeAir EPA361000BC | Portable 4 | Portable 4 | 30 min | | | No cooling Blown Fuse - completed |
| AHU 6 | ChangeAir 955-013-299 | Portable 6 | Portable 6 | 30 min | | | Pitted Contactor |
| KEF 1 | Greenheck CUBE140-7-6 | High Roof | Kitchen | 15 min | | | |
| KEF 2 | Greenheck CUBE180-20 | High Roof | Café | 15 min | | | Motor Bearings shot needs A28 Belt (Not in use) |
| KEF 3 | Greenheck CUBE160 | Bwing Low Roof | Café | 15 min | | | No Belt needs A28 - Completed |
| Exhaust Fan 1 | Cook 165VCR | High Roof | | 15 min | | | |
| ADF 1 | Cook 165VCR | High Roof | | 15 min | | | |
| ADF 2 | Cook 165VCR | High Roof | | 15 min | | | |
| ADF 3 | Cook 165VCRH | High Roof | | 15 min | | | |
| ADF 3 | Cook 165VCRH | High Roof | | 15 min | | | |
| ADF 6 | Cook 165VCR | High Roof | | 15 min | | | |
| ADF 7 | Cook 165ACRUX | High Roof | | 15 min | | | |
| ADF 8 | Cook 100ACRUL | High Roof | | 15 min | | | |
| ADF 9 | Cook 165VCR | High Roof | | 15 min | | | |
| ADF 11 | Greenheck CURE -120-A | High Roof | | 15 min | | | |
| ADF 12 | Cook 150ACRUH | High Roof | | 15 min | | | |
| ADF 13 | Greenheck CURE-95-4 | High Roof | | 15 min | | | |
| Unknown | Cook 165VCRH | High Roof | | 15 min | | | |
| CU 1 | Trane RAUCC605B1532 | Bwing Low Roof | AHU 1 | 45 min | | | Trane was on site to look at the unit for Disconnection due to roofing |

Administrative 30 min