

TEMPLEMEAD

Equipment	Manufacturer / Model/Serial	Location	What it Serves	Time Spent	Filters	Belts	Repairs Needed
AHU	Change Air Model CAE1000PAVDP / 27170073G	Portable 201		30 min			1/2 Heat and Compressor Contactor pitted / indoor fan motor has bearing lay and makes a knocking sound - Completed
AHU	Change Air CAE1000PAVPPF12KW	Portable 202		30 min			
FCU	Eng Air NA	Room 154		30 min		(1of) AX36	Pulleys grooved and fan Bearings have a lot of play - Completed
Exhaust Fan 2	Greenheck Cube141-5 / 03D29377			30 min			Motor has bad bearings and is noisy need to be replaced - pulleys are also rusted s/b replaced - Completed
Exhaust Fans (4of)		Roof		1 hour			
Condensor (Chiller)	N/A	Roof		45 min			
Chiller	Carrier 30HXA136RZE140KA / 4002Q02044	Mechanical Room		45 min			
AHU 1	Eng Air IM-8-C / 34399-3 AHU1	Mechanical Room		45 min			
MUA 1	Eng Air IM-15C / 343991-HRU1	Mechanical Room		45 min			
Return Fan 1	Trane	Mechanical Room		45 min			
Administrative 20 min							