

## TIFFANY HILLS

Equipment	Model/Serial	Location	What it Serve	Time Spent	Filters	Belts	Repairs Needed or Repaired
AHU 1	EngAir LM8C / M13882-AHU1		Various Areas	45 min	(3of) 16x20x2 - Pleated (3of) 20x20x2 - Pleated	(1of) B72 (1of) B68	Needs new Belts - Bearings Greased
HRV-1	EngAir FWB313C0 / M13882 HRV1		Gym	45 min	(15of) 20x24x2 - Pleated (3of) 24x24x2 - Pleated	(2of) B85 (2of) BX85	Needs new Belts - Bearings Greased
RTU 1	EngAir FWA52CO / M13882 RTU 1		Main Offices	45 min	(1of) 24x24x2 - Pleated	(1of) A43 (1of) A35	Belts need to be replaced
RTU 2	EngAir FWEA62CO / M13882 RTU2			45 min	(1of) 12x24x2 - Pleated (1of) 24x24x2 - Pleated	(1of) A39	Needs new Belts - Bearings Greased
AHU	ChangeAir CAE1000APA VPD / 1804 1055F	Room 103		30 min	Washable		Electric Heat contactor needs replacing 2 pole 24v coil
AHU	Changeair CAE100A PA VPD / 1798 1055F	Room 104		30 min	Washable		
AHU	Changeair CAE1000A PA VPD / 1806 1045f	Room 102		30 min	Washable		Heating contactor pitted
AHU	Changeair CAE 1000A PA VPD / 1799 1055f	Room 101		30 min	Washable		
AHU	Changeair CAE 4036 PA ERWE / 1308 1118E	Room 107		30 min	(2of) 18x18x2 - Pleated		
MUA	EngAir LM10-C / M16838ERV	Mechanical Room		60 min	(16of) 20x24x2 (8of) 24x20x2	B74 5L830	Changed Broken B74 used site stock
RTU (HVAC2)	Carrier 48HCFD11A3M1DT3J0 / 1414P93766		Gym	30 min	(4of) 16x16x2 (4of) 20x20x2	AX54	Unit is currently off waiting for work to be done - Completed
RTU (HVAC4)	Carrier 48HCEA05A05A2M1ADT3C0 / 1516C86076		Adminstration	30 min	(2of) 16x25x2 (4of) 16x16x2	AX39	
RTU (HVAC1)	Carrier 48HCFD11A3M1DT3J0 / 1416P93765		Gym	30 min	(2of) 16x25x2 (4of) 20x20x2	AX54	
RTU (HVAC3)	Carrier 48HCEA06A2M1ADT3C0 / 1516C86100		Library	30 min	(2of) 16x25x2 (4of) 16x16x2	AX38	
Exhaust Fan 12	DX08B / D16AW11856			15 min		3L210	
Exhaust Fan 13	Pennberry FX10B / D16W115857			15 min		4L230	
RTU (HVAC5)	Carrier 48HCEA07A2M1 DT3C0 / 1316P93666	Lower Roof	Daycare	30 min	(2of) 16x25x2 (4of) 16x20x2	AX52	
Exhaust Fan 11	Pennberry DX08B / D16AW11855			30 min		3L210	Needs new Belt - Completed
Exhaust Fan 10	BX11B / D16AW11854			15 min		4L230	
RTU (HVAC6)	Carrier 48HCEA07A2M1 / 1316P3665	Lower Roof	Daycare	30 min	(2of) 16x25x2 (4of) 16x20x2	AX57	Filters s/b replaced soon - Completed
Fan Coil (FC2.13)	EngAir RUV1200-C	Classroom 222	room 222	30 min	(1of) 20x24x2		
Fan Coil (FC1.10)	EngAir RUV1200-C	Classroom 124	room 124	20 min	(1of) 20x24x2		
Fan Coil (FC1.10)	EngAir RUV1200-C	Classroom 125	room 125	20 min	(1of) 20x24x2		
Fan Coil (FC1.2)	EngAir RUV1200-C	Classroom 128	room 128	20 min	(1of) 20x24x2		
Fan Coil (FC 1.3)	EngAir RUV1200-C	Classroom 109	room 109	20 min	(1of) 20x24x2		

Administrative 30 min