

Richard Beasley School
80 Currie Street
Hamilton, ON
L8T 3M9

September 11th, 2020

Dear Mr. Sokolowski,

VCI CONTROLS has conducted a preliminary check of the HVAC systems at the above-mentioned location. At the time of inspection, and at the completion of the repairs all of the HVAC systems were functioning at manufactures specifications.

No additional work is required

Regards,

Jeffrey Morneau

National Service Manager
VCI CONTROLS INC.