

**REQUEST FOR BULK SAMPLE
ANALYTICAL SERVICES**

875 Main St. W., Unit L-2-9
Hamilton, ON L8S 4R9

Analyzed by: MB
Reviewed by: EL
Report Sent by: EL

Project Name: Rousseau School		Results To: ① ravery@hwdsb.on.ca ③ stodai@hwdsb.on.ca Tel: 905-527-5092 Ext. 2732	
Project #:	Building #:	Ph.: ⑨ Jbambury@hwdsb.on.ca	
Submitted By: John Mercer		Copy 10:	
Date:	W.O. #: 307688	Invoice Required: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
# of Samples: ⑥	Date Required: asap	<input checked="" type="checkbox"/> RUSH <input type="checkbox"/> REG.	

SAMPLE#	MATERIAL/SYSTEM/LOCATION	RESULT
① Location ID# 3453	Room 197 - Floor tile (Beige)	a) ND b) ND
② ↓ ↓	↓ ↓	a) ND b) ND
③ ↓ ↓	↓ ↓	a) ND b) ND
④ Location ID# 3454	Room 199 - Floor tile (Beige)	a) ND b) ND
⑤ ↓ ↓	↓ ↓	ND
⑥ ↓ ↓	↓ ↓	ND

TO BE COMPLETED BY LAB PERSONNEL ONLY		LAB REF. #: 6167697
Received By:	Date: APR 06 2017	EL
Analyzed By: MB	Date: 17-04-06	

left msg. 1:20pm



REQUEST FOR BULK SAMPLE ANALYTICAL SERVICES

MS
JC
EL

875 Main St. W., Unit L-2-9
Hamilton, ON L8S 4R9

Project Name: Rousseau School		Results To:	
Project #:	Building #:	Ph.:	Fax:
Submitted By: John Mercer		Copy To:	
Date:	P.O. #: 307688	Invoice Required: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
# of Samples: (6)	Date Required: asap	<input checked="" type="checkbox"/> RUSH	<input type="checkbox"/> REG.

SAMPLE#	MATERIAL/SYSTEM/LOCATION	RESULT
① Location ID# 3453	Room 197 - Floor tile (Beige)	a) MID
② ↓ ↓	↓ ↓	b) MID
③ ↓ ↓	↓ ↓	c) MID
④ Location ID# 3454	Room 199 - Floor tile (Beige)	d) MID
⑤ ↓ ↓	↓ ↓	e) MID
⑥ ↓ ↓	↓ ↓	f) MID

TO BE COMPLETED BY LAB PERSONNEL ONLY		LAB REF. #: 1157617
Received By:	Date:	
Analyzed By:	Date: 7/11/06	

left msg. 1/20/06