

SCHOOL NAME: Bernie
Custis

Unit Type and Tag	Model	Serial Number	Unit Location	Serves	Time to Complete Check (Minutes)	Requires Immediate Attention to Maintain Ventilation (Y/N)	Materials	Comments
HVAC-2	RN-060-4-0-E009-3EB	210802-BNGX67107	Upper Roof	2nd Floor West	45	N	12x24x2 pl 24 B66 x2	
HVAC-3	RN-026-4-0-EB09-3CB	201802-BNGS67107	Upper Roof	Ground Floor West	45	N	24x24x2 pl 8 B66 x2	Changed Filters
HVAC-4	RN-025-4-0-EB09-341B	201801-BNGR67091	Upper Roof	Science	45	Y	20x25x2 pl 6 16x20x2 pl 6	No 16x20x2 pl on site. Need to be changed
MUA-1	SDM-75-CH-BDD-LMN-C-MV	38155-180413	Upper Roof	Staff Room	45	N	16x20x2 pl 6 B56 x2	Changed Filters
HVAC-6	RN-016-4-0-EB09-34B	201802-BNGM67092	Upper Roof	Kitchen/Servery	90	N	20x25x2 pl 6	Variable pitch pulley found come apart. Reassembled and adjusted belt tension. Changed Filters
HVAC-7	RN-030-4-0-EB09-34B	20180-BNGM67093	Upper Roof	Admin Office/Guidance	45	N	20x25x2 pl 6 B57	Changed Filters, Belt found off. Reinstalled and adjusted tension
ERV-1	RN-016-4-0-0000-38B	201802-BNGM67097	Upper Roof	Building	45	N	20x25x2 pl 6 16x20x2 pl 6	Changed filters
HVAC-5	RN-050-4-0-EB09-3DB	201802-BNGW67102	Upper Roof	3rd Floor West	45	N	12x24x2 pl 24 B65 x2	Filters clean
ERV-2	RN-016-4-0-EB09-B4B	201802-BNGM7098	Lower Roof	Building	45	N	25x25x2 pl 6 16x20x2 pl 6	Filters clean
HVAC-11	RN-050-4-0-EB09-3DB	201802-BNGW67106	Lower Roof	Third and Ground Floor Classrooms	45	N	12x24x2 pl 24 B64 x2	Filters clean
HVAC-9	RN-070-4-0-EA09-3ED	201802-BNGY67104	Lower Roof	Gym and Fitness	45	N	24x24x2 pl 24 B62 x2	Filters clean
HVAC-8	RN-040-4-0-EB09-3CB	201802-BNGV67103	Lower Roof	2nd Floor East	45	N	24x24x2 pl 24 B66 x2	Filters clean
HVAC-10	RN-031-4-0-EB09-3CB	201802-BNGV67105	Lower Roof	Cafeteria	45	N	24x24x2 pl 8 18x24x2 pl 8	Filters clean
EF13	DX12B	D18EZ93891	Upper Roof	Fit Room #2040	15	N	4L250	Belt Loose
EF12	DX12B	D18EZ9727	Upper Roof	Exercise Room #2042	15	N	4L250	Belt loose
EF28	DX11B	D18FZ21633	Upper Roof	Mech Room #3032	15	N	4L230	good
EF24	FX13B	D18EZ18136	Upper Roof	Gen. Science # 3030	15	N	4L230	Belt Worn
EF23	FX13B	D18GZ26356	Upper Roof	Physics #3029	15	N	4L230	Belt Worn
EF22	FX13B	D18EZ18137	upper Roof	Chemistry #3028	15	N	4L230	good
EF19	FX12BH	D18EZ18132	upper Roof	Exhaust fume hood	15	N	4L210	good
EF18	FX08B	D18FZ73319	upper Roof	Prep Room #3027	15	N	4L210	good
EF17	FX13B	D18EZ18129	upper Roof	Biology #3026	15	N	4L230	good
EF16	FX13B	D18EZ18130	upper Roof	Gen Science #3025	15	N	4L230	good
EF15	FX13B	D18EZ18131	upper Roof	Gen Science #3024	15	N	4L230	good
EF20	FX12BH	D18EZ18133	upper Roof	Fume Hood	15	N	4L230	good
EF21	FX12BH	D18EZ18134	upper Roof	Fume Hood	15	N	4L230	good
EF??	FX13B	K18AK51587	upper Roof	?	15	Y	4L220	Belt Cracked
HVAC-1	RN-026-4-0-EB09-3CB	201802-BNGS7100	upper Roof	Library	45	Y	24x24x2 pl 8 18x24x2 pl 8	18x24x2 filters not on site and require changing