

Unit Type and Tag	Model	Serial Number	Unit Location	Serves	Complete Check	Immediate	Materials	Comments
window A/C	comfortaire		east learning resource	east learning resource	15 N		washable	good
window A/C	Bryant		west learning resource	west learning resource	15 N		washable	
EF1			west roof	class rooms	15 Y			not operating
EF2			west roof	class rooms	15 N			good
EF3	G075DGEXQD	14203392	west roof	class rooms	15 Y			not operating
EF4	G080DGEXQD	14298814	west roof	class rooms	15 N			good
EF5	G080DGEXQD	14362695	west roof	class rooms	15 N			good
EF6	G075DGEXQD	14203393	west roof	class rooms	15 N			good
EF7	GB0814XADR2	15077537	west roof	class rooms	15 Y		1-3L190	needs belt
EF8			west roof	class rooms	15 N			good
EF9			west roof	class rooms	15 Y			not operating
EF10	GB0816X	702	west roof	class rooms	15 Y		1-3L190	needs belt, not operating
EF11	GB0816X	702	west roof	class rooms	15 Y		1-3L210	needs belt , not operating
EF12			centre roof	class rooms	15 N			good
EF13	GB070DGEXQD	15522613186	centre roof	class rooms	15 N			good
EF14			east roof	class rooms	15 N			good
EF15			east roof	class rooms	15 Y			not operating
EF16			east roof	class rooms	15 N			good
EF17	JennAir 241CKG		high roof	gym	15 Y		1-A64	not operating, not worth repairing (too old)
EF18	JennAir 241CKG		high roof	gym	15 Y		1-A64	motor faulty, not worth repairing (too old)