

- Building Performance
- Lighting Solutions
- Building Automation Systems
- Thermal Energy Systems
- Mechanical Services
- Energy Retrofits

Cecil B Stirling School 340 Queen Victoria Dr Hamilton, ON L8W 1T9

September 11th, 2020

Dear Mr. Sokolowski,

VCI CONTROLS has conducted a preliminary check of the HVAC systems at the above-mentioned location. At the time of inspection, and at the completion of the repairs all of the HVAC systems were functioning at manufactures specifications.

Regards,

Jeffrey Morneau

National Service Manager VCI CONTROLS INC.

