



August 20, 2020

Dr. J. Edgar Davey School
99 Ferguson Ave N
Hamilton, ON

Michael Sokolowski:

Inspection and deficiencies on ventilation systems for this site have all been repaired/completed.
Units all running up to manufacturers specifications.

Regards,

Chamberlain Building Services