

### DR DAVEY SCHOOL

Equipment	Model/Serial	Location	What it Serves	Time Spent	Filters	Belts	Repairs Needed or Repaired
HRV 1	EngAir FWB354-DG270-0 / 45723 HRV1			60 min	(30of) 20x24x2	(4of) B87 (2of) B123	Greased Bearings
Supply Fan 1	Greenheck SWB216-16-GGW-TH-X / 11977 834 1002			30 min		(1of) AX35	Greased Bearings
Exhaust Fan 6				30 min		(1of) 3L280	
HP 17	ClimateMaster TSD02AHD40CLVS / M15245903		Room 139	1.5 hrs	(2of) 15-3/4 x 30 x1		Cleaned strainer
HP 18	ClimateMaster TSD070AND40CRDS / M1527360		Room 139	1.5 hrs	(2of) 15-3/4 x 30 x1		Cleaned strainer
HP 22	ClimateMaster TSV060AND40CLVS / M15247340		Room 227	60 min	(1of) 15-3/4x30x1 (of) 19-3/4x30x1		Needs new Blower - cleaned strainer - Completed
HP 30	ClimateMaster TSD024AHD40CLDS / N10617670		room 209	1.5 hrs	(1of) 24x27-3/4x1		Sludge in water lines - cleaned strainer

Administrative 20 min