

September 10, 2020

Hamilton Wentworth District School Board Flamborough Centre School 922 Centre Road Hamilton, ON L8N 2Z7

Attn: Michael Sokolowski

Good afternoon,

As per Smith and Long Mechanical work order numbers: 159888 and 160633 all equipment on the work orders have been inspected and all approved quoted deficiencies have been completed. All equipment on the work orders are running up to manufacturers specifications as of September 10, 2020.

Sincerely,

Smith and Long Mechanical Ltd

SMITH AND LONG MECHANICAL LTD 115 Idema Road, Markham, ON L3R 1A9 T 416.391.0443 • smithandlong.com Emergency line: 1.800.817.0622