SCHOOL NAME: Glen Brae

| Unit Type and Tag | Model | Serial Number | Unit Location | Serves | Time to Complete Check (Minutes) | Requires Immediate Attention to Maintain Ventilation (Y/N) | Materials | Comments |
|-------------------------|---------|---------------|---------------|------------|---|---|-----------------|--|
| EF2, EF | Unknown | Unknown | Roof | Building | 15 | N | A53(1) | Not Operable |
| Jnknown, EF | Unknown | Unknown | Roof | Building | 15 | | A46(1) | Not Operable. Belt Done |
| EF6, EF | Unknown | Unknown | Roof | Building | 15 | | A33(1) | Not Operable |
| EF5, EF | Unknown | Unknown | Roof | Building | 15 | | | Not Operable |
| F9, EF | Unknown | Unknown | Roof | Building | 15 | N | 4L250 | Not Operable |
| EF3, EF | Unknown | Unknown | Roof | Building | 15 | N | | Not Operable |
| F4, EF | Unknown | Unknown | Roof | Building | 15 | N | 4L260(1) | Not Operable |
| F8, EF | Unknown | Unknown | Roof | Building | 15 | N | A53(1) | Not Operable |
| EF1, EF | Unknown | Unknown | Roof | Building | 15 | Υ | 4L260(1) | Belt Adjustment Needed, Not Operable |
| EF7, EF | Unknown | Unknown | Roof | Building | 15 | N | A53(1) | Not Operable |
| Jnknown , EF | Unknown | Unknown | Roof | Building | 15 | N | A42(1) | Not Operable, Belt Done, Belt Alignment Needed |
| Unknown, Window AC Unit | Unknown | Unknown | Room 205 | Room 205 | 15 | N | Washable Filter | Cleaned Filter |
| Unknown, Window AC Unit | Unknown | Unknown | Library | Library | 15 | N | Washable Filter | Cleaned Filter |
| Jnknown, Window AC Unit | Unknown | Unknown | Library | Library | 15 | N | Washable Filter | Cleaned Filter |
| Jnknown, EF | Unknown | Unknown | Art Room | Art Room | 15 | N | 4L40 | |
| Unknown, Portable AC | Unknown | Unknown | Staff Room | Staff Room | 30 | | Washable Filter | Cleaned Filter |
| Unknown, Portable AC | Unknown | Unknown | Staff Room | Unused | 30 | N | Washable Filter | Cleaned Filter |