



August 27, 2020

Glenwood School  
150 Lower Horning Rd  
Hamilton, ON

Michael Sokolowski:

Inspection and deficiencies on ventilation systems for this site have all been repaired/completed.  
Units all running up to manufacturers specifications.

Regards,

Chamberlain Building Services