

SCHOOL NAME: Hill Park

Unit Type and Tag	Model	Serial Number	Unit Location	Serves	Complete Check	Immediate	Materials	Comments
AHU1, RTU	TBA250DXC20	CN695AHU1	East Roof	Building	45	N	20x20x2(6) B60(2) B57(2)	Filters Done, Belts Needed
AHU3, RTU	TBA250DXC20	CN695AHU3	East Roof	Building	45	N	20x20x2(6) B58(4)	
Unknown, EF	Unknown	Unknown	East Roof	Building	15	Y	A24	Belt Needed
Unknown, HP	RZQ18PVJU9	A007331	East Roof	Building	30	N	Washable Filters	
Unknown, HP	RK12NMVJU	G005417	East Roof	Building	30	N	Washable Filters	
Unknown, HP	RK12NMVJU	G005410	East Roof	Building	30	N	Washable Filters	
Unknown, HP	Unknown	Unknown	East Roof	Building	30	N	Washable Filters	
Unknown, HP	RZQ18PVJU9	A007340	East Roof	Building	30	N	Washable Filters	
AHU4, RTU	TBA250DXC25	CN698AHU4	East Roof	Building	45	Y	20x24x2(6) B66(3) B58(2)	Filters Done, Belts Needed
AHU2, RTU	TBA250DXC20	CN695AHU2	East Roof	Building	45	N	20x20x2(6) B58(4)	Filters Done
Unknown, EF	Unknown	Unknown	East Roof Penthouse	Cafeteria	15	N	B85(2)	
Unknown, EF	Unknown	Unknown	East Roof	Building	15	Y	4L280(1)	Belt Needed, Not Operable
Unknown, EF	Unknown	Unknown	East Roof	Building	15	N	A25(1)	Belt Adjustment
Unknown, EF	Unknown	Unknown	East Roof	Building	15	N	A33	Belt Needed, Not Operable
Unknown, EF	Unknown	Unknown	Central Roof	Building	15	Y	AM31	Fan out of alignment rubbing on housing
Unknown, SF	Unknown	Unknown	Central Roof Penthouse	Boys Gym	45	N	20x20x2(12) B144(2)	Not Operable
Unknown, SF	Unknown	Unknown	Central Roof Penthouse	Girls Gym	45	N	20x20x2(8) 4L1000(1)	
Unknown, RTU	YSD180GWRHA0VDN	192510228D	West Roof	Building	45	N	20x20x2(4) 20x25x2(4) BX64	Filters Needed
Unknown, RTU	YSC120FWEHA1VD	164813150L	West Roof	Building	45	N	20x25x2(4)	Filters Needed
Unknown, EF	Unknown	Unknown	West Roof	Building	15	Y	A25	Belt Needed, Tighten Pulley
Unknown, EF	Unknown	Unknown	West Roof	Building	15	Y	A24	Belt, Motor Seized
Unknown, EF	Unknown	Unknown	West Roof	Building	15	N	4L250(1)	Belt Needed, Needs Adjustment
AHU6, RTU	TBA250DXC20	CN695AHU6	West Roof	Building	45	Y	20x20x2(6) B60(2) B58(2)	Filters Done, Belts Needed
AHU8, RTU	TBA650DXC30	CN695AHU8	West Roof	Building	45	N	20x24x2(9) B80(3) B70(2)	Filters Needed
AHU7, RTU	TBA300DXC25	CN695AHU7	West Roof	Building	45	Y	20x24x2(6) B62(2) B58(2)	Not Operable
AHU5, RTU	TBA300DXC25	CN695AHU5	West Roof	Building	45	N	20x24x2(6) B62(2) B58(2)	Filters Needed
Unknown, EF	Unknown	Unknown	West Roof	Building	15	N	4L240(1)	Belt done
Unknown, EF	Unknown	Unknown	West Roof	Building	15	N	A20(1)	
Unknown, EF	Unknown	Unknown	West Roof	Building	15	Y	A20(1)	Belt done
Unknown, SF	Unknown	Unknown	Low Roof Penthouse	Cafeteria	45	N	20x24x2(6) 20x20x2(2) A112(2)	
Unknown, RTU	48HCRA06A2A5A0F3A0	3118C88438	Low East Roof	Building	45	N	AX39(1) 16x16x2(4)	
Unknown, RTU	48HCTA06A2A5A0F3A0	3118C88508	Low East Roof	Building	45	N	AX38(1) 16x16x2(4)	
Unknown, RTU	ZYG08T2B1AB1B323A2	N1H7024966	Low East Roof	Building	45	N	20x20x2(4) A(48)	
Unknown, RTU	YHC048A3EMA	336100471L	Low East Roof	Building	45	N	20x25x1(2) A26(1)	
Unknown, EF	Unknown	Unknown	Low East Roof	Building	15	N		
Unknown, RTU	48HCDB04A2A5A0F3A0	3318C89697	Low East Roof South	Building	45	N	16x25x2(1) AX38(1)	
Unknown, RTU	48HCED08A2A5A6F3G0	3118P80268	Low East Roof South	Building	45	N	20x20x2(4) A48(1)	Filters Done
Unknown, EF	Unknown	Unknown	Low East Roof South	Building	15	N	4L330(1)	Not Operable
HVAC3, RTU	YCD048CWHABE	L15101010D	Low West Roof	Building	45	N	10x25x1(4)	Filters Needed