

Macdonald

Unit Type and Tag	Model	Serial Number	Unit Location	Serves	Check (Minutes)	Attention to	Materials	Comments
UV13	VUV1200	Q1230-UV13	Room 131	Room 131	30	N	12.75x29.5x1(2)	Filters Done
Unknown, UV	Unknown	6VL8030300	Room 136	Room 136	30	N	9.25x36.25x1(2)	Filters Done
Unknown, UV	Unknown	6VL8030100	Room 137	Room 137	30	N	9.25x36.25x1(2)	Filters Done
Unknown, UV	Unknown	6VL8030400	Room 138	Room 138	30	N	9.25x36.25x1(2)	Filters Done
Unknown, UV		6VL8030200	Room 132	Room 132	30	N	9.25x36.25x1(2)	Filters Done
Unknown, Window AC Unit	Unknown	Unknown	Room 132	Room 132	30	N	Washable Filter	Cleaned Filter
UV12	VUV1200	Q1230-UV12	Room 145	Room 145	30	N	12.75x29.5x1(2)	
UV11	VUV1200	Q-1230-UV11	Room 145	Room 145	30	N	12.75x29.5x1(2)	Filters Done
UV10	VUV800	Q1230-UV10	Room 146	Room 146	30	N	12.75x19x1(2)	Filters Done
UV9	VUV800	Q1230-UV9	Room 146	Room 146	30	N	12.75x19x1(2)	Filters Done
UV8	VUV1600	Q1230-UV8	Room 147	Room 147	30	N	12.75x38x1(2)	Filters Done
UV7	VUV1600	Q1230-UV7	Room 148	Room 148	30	N	12.75x38x1(2)	
UV6	VUV1200	Q1230-UV6	Room 120	Room 120	30	N	12.75x29.5x1(2)	
UV5	VUV1200	Q1230-UV5	Room 105	Room 105	30	N	12.75x29.5x1(2)	Filters Done
UV3	VUV1200	Q1230-UV3	Room 106	Room 106	30	N	12.75x29.5x1(2)	
UV4	VUV1200	Q1230-UV4	Room 113	Room 113	30	N	12.75x29.5x1(2)	Filters Done
UV2	VUV1200	Q1230-UV2	Room 112	Room 112	30	N	12.75x29.5x1(2)	Filters Done
UV1	VUV1200	Q1230-UV1	Room 110	Room 110	30	N	12.75x29.5x1(2)	Filters
AH1	Unknown	Unknown	Fan Room	Gym	45	N	16x25x2(2)20x25x2(2)M) A71(1)	Filters Done, Filter stuck in rack can't be changed, Heating Coil Cleaned
AH2	Unknown	Unknown	Fan Room	UV Supply	45	N	16x25x2(2)20x25x2(4)M) AX68(1)	Filters Done, Heating Coil Cleaned
Unknown, EF	Unknown	Unknown	Roof	Washrooms	15	N	4L260(1)	Belt Needed
Unknown, EF	Unknown	Unknown	Roof	Building	15	Y	A40(1)	Belt Needed
Unknown, EF	Unknown	Unknown	Roof	Building	15	Y	Unknown Belt	Motor seized, Belt
Unknown, EF	Unknown	Unknown	Roof	Building	15	N	Unknown Belt	
Unknown, EF	Unknown	Unknown	Roof	Building	15	N	3L190(1)	