

LAWFIELD SCHOOL

Equipment	Model/Serial	Location	What it Serves	Time Spent	Filters	Belts	Repairs Needed or Repaired
HRU 1	Enmar DF1000HE-12 / S0000598	High Roof	Mutiple Areas	45 min			Heat Wheel not turning - Completed
Exhaust Fan 2	Greenheck GB 0814X / 108811960705	High Roof	Staff workroom 1 RM 231	15 min			Motor Bearings noisy and belt cracked (3L190) - Completed
Exhaust Fan 6	Greenheck GB 0814X / 108811960705	High Roof	Washrooms 2nd Floor	15 min			Motor Bearings noisy and belt cracked (3L180) - Completed
RTU 1	Trane YHC033A3RLA14 / 731102500L	Low Roof	Daycare	45 min			Cracked Belt replaced with A34 site stock
RTU 2	Trane YHC033A3RLA14 / 731102500L	Low Roof	Daycare	45 min			Limit switch for heating faulty - Completed
AHU 1	ChangeAir CAE1000PAVPF / 04270290C	Portable 1	Portable 1	30 min			Unit dirty - completed
AHU 2	ChangeAir CAE1000PaVPF / 09930258H	Portable 2	Portable 2	45 min			Dirty filter 1st stage heating contactor arching and pitted - Completed
AHU 3	ChangeAir CAE1100 / 32779019F	Portable 3	Portable 3	30 min			Filter very dirty not allowing Condensate to drain out - Completed
AHU 4	ChangeAir CAE1000PAVD / 09840258H	Portable 4	Portable 4	45 min			Unit very dirty - Filters installed wrong - compressor contactor arching and pitted - Completed
AHU 5	ChangeAir CAE1000PAVD / 03910290C	Portable 5	Portable 5	45 min			Unit very dirty - needs new door switch - Completed
AHU 6	ChangeAir CAE1000PAVPF / 14820216G	Portable 6	Portable 6	30 min			

Administrative 30 min