

Henderson

Unit Type and Tag	Model	Serial Number	Unit Location	Serves	Complete	Immediate	Materials	Comments
AHU1	48TFE014-A-111-	2903G50853	South Roof	Building		Y	B47(1) 20x20x2(4)	Belt Needed
AHU3	TBA-250/DX-C20/RA	CN-2396	South Roof	Building		Y	16x20x2(4)20x20x2(2) B82(1) B62(1)	Filters, Belts Done)
AHU2	TBA300/DX-C25/RA	CN-2396	South Roof	Building		Y	B74(1) B79(2) 20x20x2(3) 16x20x2(6)	Belts, Filters Done
EF14	Unknown	Unknown	South Roof	Building		Y	A24(1)	Belt done
EF15	Unknown	Unknown	Central Roof	Building		Y	A21(1)	Belt Done
AHU5	48TFE008-A-111HQ	3103G20570	Central Roof	Building		Y	16x20x2(4) A48(1)	Belt, Filters done
EF16	Unknown	Unknown	Central Roof	Building		Y	A25(1)	Belt done, Adjustment Needed
AHU7	TBA-250/DX-C20/RA	CN-2396	Central Roof	Building		Y	B66(1)B71(1) 20x20x2(2) 16x20x2(4)	Belts, Filters Needed
AHU8	TBA-250/DX-C20/RA	CN-2396	Central Roof	Building		Y	B66(1), B80(1) 20x20x2(2) 16x20x2(4)	Belts, Filters Needed
AHU10	TBA-300/DX-C25/RA	CN-2396)	North Roof	Building		N	B66(1)B80(1) 20x20x2(3) 16x20x2(6)	Belts, Filters Needed
EF19	Unknown	Unknown	North Roof	Building		Y	A21(1)	Belt Needed
EF18	Unknown	Unknown	North Roof	Building		Y	A21(1)	Shaft/Bearings Failed, Replace Fan
EF17	Unknown	Unknown	North Roof	Building		N		
AHU11	TBA-250/DX-C20/RA	CN-2396	North Roof	Building		Y	B82(1) B64(1) 16x20x(4) 20x20x2(2)	Belts, Filters Needed
Unknown EF	Unknown	Unknown	North Roof(End)	Building		Y		Not Operable
Unknown EF	Unknown	Unknown	North Roof(End)	Building		Y		Not Operable
Unknown EF	Unknown	Unknown	North Roof(End)	Building		Y	A47(1)	Not Operable, Needs Belt
Unknown EF	Unknown	Unknown	North Roof(End)	Building		Y	Unknown Belt	Not Operable)
AHU12	48TFE006-A-111HQ	1103G30232	North Roof	Building		Y	A39(1) 16x25x2(2)	Needs Belt, Filters
AHU9	48TFE008-A-111HQ	2903G40584	North Roof	Building		N	A48(1) 16x20x2(4)	
Unknown EF	Unknown	Unknown	North Roof	Building		N	Noted Not In Service	Noted, Not In Service
Unknown EF	Unknown	Unknown	North Roof	Rangehood		Y	3L220(1)	Belts, Bot Operable
Unknown EF	Unknown	Unknown	North Roof	Rangehood		Y	3L220(1)	Belts, Bot Operable
Unknown EF	Unknown	Unknown	North Roof	Building		N	A33(1)	Not Operable
Unknown EF	Unknown	Unknown	North Roof	Building		N	A33(1)	Not Operable
AHU4	YCD180	Z33100475D	Low Roof	Building		Y	B68(1) 16x20x2(4) 20x20x2(4)	Evap Cleaning, clean economizer filters
RF	Unknown	Unknown	Boiler Room Mezzanine	Building		N	A128(2)	
SF	Unknown	Unknown	Boiler Room Mezzanine	Building		N	A105(2) 20x25x1(9)(M)	
Unknown MUA	Unknown	Unknown	Low Roof	Building		Y	16x20x2(6) B40(1)	Motor Bearings, Not Operable
Unknown EF	Unknown	Unknown	Low Roof	Building		N	B30(1)	Belt Adjustment
Unknown EF	Unknown	Unknown	Low Roof	Building		N		Not Operable
Unknown EF	Unknown	Unknown	North Roof	Building		N		Noted Not In Service
Unknown SF	Unknown	Unknown	Gym Mezzanine	Girls Changeroom			A120(2) 20x25x1(8)(M)	Filters Needed, Clean Coil
Unknown RF	Unknown	Unknown	Gym Mezzanine	Gym Recirculating Fan		N	A112(2)	Clean RF Grill
Unknown RF	Unknown	Unknown	Gym Mezzanine	Boys Changeroom/Gym		Y	B105(2) 20x25x1(9)(M)	Broken Flex Connector, dirty coil, Fresh air dampers not operable
Unknown SF	Unknown	Unknown	Gym Mezzanine	Girls Gym Supply		Y	20x20x1(6)(M) A90(2)	Dirty Coil
Unknown EF	Unknown	Unknown	Gym Mezzanine	Gym Exhaust		Y	4L550(2)	Belts Needed
Unknown SF	Unknown	Unknown	Gym Mezzanine	Shop Supply			20x25x1(9) B136(2)	Dirty Coil
Unknown RF	Unknown	Unknown	Gym Mezzanine	Shop Return			B75(2)	Needs Belt
Unknown MUA	MPB-11-300	Unknown	Low Roof	Cafeteria		Y	16x20x2(6) B40(1)	Belt, Filters Needed, Motor Seized, Pulley Worn