

QUEEN MARY SCHOOL

Equipment	Model/Serial	Location	What it Serves	Time Spent	Filters	Belts	Repairs Needed or Repaired
AHU 1	Trane MCCA025AACOD000 / L95B11902	Mechanical Room 1st Floor		45 min	(4of) 20x25x2 (4of) 16x25x2	(2of) BX62	Filters needed to be changed - caretaker stated hew ill be changing in the this week (Aug 17)
AHU 2	Trane MCCA025AACOD000 / K95B13341	Mechanical Room 1st Floor		45 min	(4of) 20x25x2 (4of) 16x25x2	(2of) BX62	
AHU 3	Trane MMCCA030HCC0EACOABOO / K95B13358	Mechanical Room 1st Floor		45 min	(10of) 16x25x2	(2of) BX62	Filters needed to be changed - caretaker stated hew ill be changing in the this week (Aug 17)
AHU 4	Trane MCCA025GAOACB000FFA00DABOOAO / K95B13378	Mechanical Room 2nd Floor		1.5 hrs	(4of) 20x25x2 (4of) 16x25x2	(2of) BX61	Found broken belt - replaced belts & adjusted motor mount to achieve proper belt tension
AHU	Trane MCCA025GAOACB000FFA00DABOOAO / K95B12750	Mechanical Room 3rd Floor		45 min	(4of) 20x20x2 (2of)20x25x2	(1of) BX48	Filters needed to be changed - caretaker stated hew ill be changing in the this week (Aug 17)
AHU	Trane MCCA021AACEACOCOOO / K95B13627	Mechanical Room 3rd Floor		45 min	(4of) 20x20x2 (4of)20x25x2	(2of) BX62	Filters needed to be changed - caretaker stated hew ill be changing in the this week (Aug 17)
AHU	Trane Model/Serial Number N/A	Gym	Gym	45 min	(4of) 20x25x2 (4of) 16x25x2	(2of) BX74	Filters needed to be changed - caretaker stated hew ill be changing in the this week (Aug 17)
AF 1	Return Air Fan			15 min		(1of) AX77	
AF 2	Return Air Fan			15 min		(1of) AX80	
AF 3	Return Air Fan			15 min		(1of) AX85	
AF 4	Return Air Fan			15 min		(1of) AX77	
AF 5	Return Air Fan			15 min		(1of) AX80	
Exhaust Fan		Generator Room		15 min			
Exhaust Fan 6		Mechanical Room 3rd Floor		15 min			
Exhaust Fan 7		Mechanical Room 3rd Floor		15 min		(1of) BX74	
Freeze Stat							Pneumatic Dampers working
Exhaust Fan		Washroom - above drop ceiling	Floor 1,2,3	60 min			
BAS				3 hours			

Administrative 45 min