

QUEEN VICTORIA

Equipment	Model/Serial	Location	What it Serves	Time Spent	Filters	Belts	Repairs Needed or Repaired
HP 1	Climate Master GSV030AHX40CLTA / 13781730	Room 308		30 min			
HP 3	Climate Master GSV018CGX40CRTA / 13576810	Room 307		30 min			
HP 9	Climate Master GSH024AHX40CLBA / 13577477	Room 325		30 min			
HP 10	Climate Master GSH036AHX40CRTA / 13576900	Room 326		30 min			
HP 14	Climate Master GSH018CGX40CRBA / 13577451	Room 321		30 min			
HP 24	Climate Master GSV024AHXHX40CLTA / 13678425	Room 207		30 min			
HP 28	Climate Master GSHV018CGX40CRDA / 13576812	Room 202		45 min			
HP 31	Climate Master GSV036AHX40CLDA / 13576891	Room 226C		60 min			
HP 33	Climate Master GSV036AHX40CLDA / 13576892	Room 226B		30 min			
HP 39	Climate Master GSV03018AHX40CLDA / 13781727	Room 101/102	Stairwell	30 min			
HP 58	Climate Master GSH018CGX40CLBA / 13577454	Room 226		60 min			
HRU	EngAir FWB354-DG160-0 / 42954 HRU1			45 min			
Ductless 1	Mits MS-A12WA / 8002146			15 min			
CU 1	Mits MS-A12WA / 8002230			15 min			
Ductless 2	Mits MS-A12WA / 8002114			15 min			
CU 2	Mits MS-A12WA / 8002430			15 min			
Cooling Tower	Evapco IRW-91-2 / 7-325251			30 min			

Administrative 30 min

ALL PIECES OF EQUIPMENT WORKING UP TO MANUFACTURES SPECS