

(2)

| HWDSB | SCHOOL: | Sir Winston Churchill | | | | Unit Ventilators in | Comments |
|--|------------------------------|--|---|----------------------------------|--|---|-----------------------------------|
| Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.) | Model | Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.) | Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.) | Time To Complete Check (minutes) | Requires Immediate Attention to maintain ventilation | | |
| EF 22 | Greencheck CUE-121-V6-4-x | East Roof (left) 4th | | 15/30/45 | Y/N | - running - O.K. | CHAMBERLAIN working on some units |
| EF 23 | Greencheck CUE-121-V6-4-x | S. East Roof (left) 4th | | 15/30/45 | Y/N | - running - O.K. | |
| EF. 15 | Dome Fan | S. East Roof (center) 4th | SE Wash Rm Academic wing | 15/30/45 | Y/N | - NOT running | |
| EF No label | Greencheck CUE-085-V6-x | S. East Roof (left) 4th | Science Room | 15/30/45 | Y/N | - running - O.K. | |
| EF. 21 | Greencheck CUE-121-V6-4-x | S. East Roof (left) 4th | S.R | 15/30/45 | Y/N | - not running. - O.K. | |
| EF | Greencheck CUE-101-V6-4-x | S. East Roof (right) | S.R | 15/30/45 | Y/N | - not operating | |
| EF 41 | Dome Fan | S. East Roof (center) | | 15/30/45 | Y/N | - not operating | |
| EF 20 | Greencheck CUE-121-V6-4-x | North East Roof | S.R | 15/30/45 | Y/N | - running - O.K. | |
| NO# | Greencheck CUE-121-V6-4-x | North east Roof | S.R | 15/30/45 | Y/N | - running. - O.K. | |
| EF 25 | Greencheck CUE-085-V6-x | N. East South Roof | S.R | 15/30/45 | Y/N | - running - O.K. | |
| EF 18 | Dome Fan | North East Roof | | 15/30/45 | Y/N | - running. - O.K. | |
| EF 19 | Greencheck CUE-121-V6-4x | North East Roof | | 15/30/45 | Y/N | - running. - O.K. | |
| AHU | Trane | Boiler Room | Boiler Room | 15/30/45 | Y/N | - High ceiling unit (no ladder) - Caretaker states it is never used → never turned on | |

FOURTH FLOOR ROOF

* Unit Ventilators in
 - Cosmetology Room (2)
 - manufacturing Room (3)
 - aviation Room (4)
 - auto shop (2)

CHAMBERLAIN working on some units

~~EF16~~

| HWDSB | SCHOOL: | Sir Winston Churchill | | | | |
|--|-----------------------------|--|---|----------------------------------|--|---|
| Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.) | Model | Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.) | Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.) | Time To Complete Check (minutes) | Requires Immediate Attention to maintain ventilation | Comments |
| EF16 | Dome Fan | Center 4th Roof | | 15/30/45 | Y/N | - Running - O.K. |
| EF32 | Dome Fan | Center 4th Roof | | 15/30/45 | Y/N | - Running - O.K. |
| EF17 | Dome Fan | Center 4th Roof | | 15/30/45 | Y/N | - Running - slight vibration (Bearings) |
| EF40 | Dome Fan | Center 4th Roof | | 15/30/45 | Y/N | - Not Running |
| EF33 | Dome Fan | Center 4th Roof | | 15/30/45 | Y/N | - Running - O.K. |
| E.F | FLOAIRE Power ventilator | Cafeteria Roof | Cafeteria | 15/30/45 | Y/N | - No power to unit - missing belt. A25 1315 |
| RTU AHU | Keeprite KRFB200G | Cafeteria Roof | Cafeteria | 15/30/45 | Y/N | - No ladder or roof access - must return with ladder |
| E | | | | 15/30/45 | Y/N | - No power to unit - broken belt 4L420 R2A |
| E.F | Dome Fan Jenn Air 183BCRA | 1st floor Roof (Beside Cafe) | Football locker Room | 15/30/45 | Y/N | - No belt - no power at unit - motor suspect |
| EF | Dome Fan Jenn Air 98CRA | 1st floor Roof (Between Cafe/Gym) | Chlorine room | 15/30/45 | Y/N | - Unit not running - Direct drive (Pool?) |
| E.F | EXH 033572 | wood SHOP | Room 1051 | 15/30/45 | Y/N | - working - O.K. |
| EF | Centrifugal Trane | 1st floor roof East | Room 1051 | 15/30/45 | Y/N | - working - O.K. - Cosmology Room |
| EF | Lawson-Taylor HDBI-120 Fan | Roof 1st floor east | MANU-factory | 15/30/45 | Y/N | - working - O.K. |
| EF | Trane Centrifugal Blower TH | Roof 1st floor East | Aviation | | | NOT IN USE |

Pool

| HWDSB | SCHOOL: | Sir Winston Churchill | | | | Requires Immediate Attention to maintain ventilation | Comments |
|--|--------------|--|---|----------------------------------|-----|--|----------|
| Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.) | Model | Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.) | Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.) | Time To Complete Check (minutes) | | | |
| Unit ventilator | Trane | Room 1028 | 1028 | 15/30/45 | Y/N | - Filters clean. Unit dirty | |
| Unit ventilator | Trane unit 1 | Room 2011 | Room 2011 | 15/30/45 | Y/N | - Filters dirty | |
| Unit ventilator | Trane unit 2 | Room 2011 | Room 2011 | 15/30/45 | Y/N | - FHP 3L210 - needs belt | |
| Unit ventilator | Trane | Room 2017 | Room 2017 | 15/30/45 | Y/N | - Filters dirty. | |
| Unit ventilator | Trane | Room 2017 | Room 2017 | 15/30/45 | Y/N | - Unit does not start | |
| Unit ventilator | Trane | Room 2022 | Room 2022 (staff) | 15/30/45 | Y/N | - Belt thrown off - reinstalled. | |
| Unit ventilator | Trane | Room 2022 | Room 2022 (staff) | 15/30/45 | Y/N | - Filter clean | |
| Unit ventilator | Trane | Room 2028 | Room 2028 | 15/30/45 | Y/N | - o.k. - operation - o.k. | |
| Unit ventilator | Trane | Room 2028 | Room 2028 | 15/30/45 | Y/N | - Filter dirty | |
| Unit ventilator | Trane | Room 2030 | Room 2030 | 15/30/45 | Y/N | - o.k. | |
| Unit ventilator | Trane | Room 2030 | Room 2030 | 15/30/45 | Y/N | - Filter dirty, | |
| Unit ventilator | Trane | Room 2031 | Room 2031 | 15/30/45 | Y/N | - o.k. | |
| Unit ventilator | Trane | Room 2031 | Room 2031 | 15/30/45 | Y/N | - Filter dirty | |
| Unit ventilator | Trane | Room 2032 | Room 2032 | 15/30/45 | Y/N | - Belt thrown - reinstalled belt | |
| | | | | 15/30/45 | Y/N | - Louvres stuck open | |
| | | | | 15/30/45 | Y/N | | |
| | | | | 15/30/45 | Y/N | | |
| | | | | 15/30/45 | Y/N | | |
| | | | | 15/30/45 | Y/N | | |
| | | | | 15/30/45 | Y/N | | |
| | | | | 15/30/45 | Y/N | | |

Please Note: Green filter media. 10 1/2 x 24"

Checked by...

* Third floor not completed
* Roof exhausts not completed

Health & Wellness → Three ceiling unit ventilators ^{Heaters} → need tall ladder. 20"
 ↳ Room 2040 Room 2042 (cabinet shop) "
 Room 2041 → manufacturing room " Room 2044 auto

| HWDSB | SCHOOL: | Sir Winston Churchill | | | | |
|--|-----------------------------------|--|---|----------------------------------|--|---|
| Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.) | Model | Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.) | Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.) | Time To Complete Check (minutes) | Requires Immediate Attention to maintain ventilation | Comments |
| AHU # AH-1 | Trane Performance climate changer | Room 2007 | Library? or office? | 15/30/45 | Y/N | -checked belts, filters, louvres. -checked operation. → o.k. |
| AHU AH-2 | Trane performance climate | Room 2007 | Library or office? | 15/30/45 | Y/N | -checked belts, filters, louvres -checked operation → o.k. |
| Return Fan RFI | Trane T31V-HF | Room 2007 | Gym Return | 15/30/45 | Y/N | -checked belts. -o.k. -Fan and interior dirty. |
| S.F SF2 | Trane 31-LM-HF | Room 2007 | Gym supply | 15/30/45 | Y/N | - Fan belts off - Filter needs to be turned |
| S.F | Trane 61P-MF | Room 2007 | Art Room | 15/30/45 | Y/N | - Replaced filters - Belts - o.k. |
| S.F -3 | Trane | Room 2007 | Auditorium | 15/30/45 | Y/N | - Needs roll filters (\$570) - Breaker off → needs further investigation |
| R.F 2 | Trane T41V-HF | Room 2007 | Auditorium | 15/30/45 | Y/N | - Belts o.k. - Unit shakes, possible bearing issue |
| SF 5 | Trane | Room 2007 | Gym Girls Lockers | 15/30/45 | Y/N | - Not working |
| E.F -2 | Trane | Room 2007 | Gym Lockers | 15/30/45 | Y/N | - motor bearings noisy |
| FC-1 | Trane | Room 2007 (ceiling) | Music Room | 15/30/45 | Y/N | 12x24x2 - Filter dirty unit - o.k. |
| SF 8 | Trane | Room 2007 | Fan room | 15/30/45 | Y/N | - Replaced filters - unit not working |
| RF-5 | Trane | Room 2007 | Art Room | 15/30/45 | Y/N | - checked belts - checked function - o.k. |
| RF-3 | Trane | Room 2007 | Fan Room | 15/30/45 | Y/N | - checked belts - function → o.k. |

Asbestos Hazard
" "
" "

Thurs Aug 27

| HWDSB | SCHOOL: | Sir Winston Churchill Secondary School | | | | |
|--|---------------------------|--|---|----------------------------------|--|---|
| Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.) | Model | Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.) | Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.) | Time To Complete Check (minutes) | Requires Immediate Attention to maintain ventilation | Comments |
| Unit (UV3) Unit ventilator - Change Air - | System Air | Room 4022 | Room 4022 | 15/30/45 | Y/N | please note: replaced Camfil Aeopleat III filters with Aeopstar pleated filters found on site. (Merv 8) - replaced filters - checked operation → O.K. |
| Unit ventilator (UV4) | System air - Change air - | Room 4021 | Room 4021 | 15/30/45 | Y/N | - replaced filters - checked operation → O.K. |
| Unit (UV5) ventilator | - change air | Room 4020 | Room 4020 | 15/30/45 | Y/N | - replaced filters - freestat tripped - reset → operation O.K. |
| Unit ventilator (UV-6) | change air | Room 4019 | Room 4019 | 15/30/45 | Y/N | - replaced filters - freestat tripped - reset - monitored operation O.K. |
| Unit ventilator (UV-2) | change air | Room 4025 | Room 4025 | 15/30/45 | Y/N | - replaced filters (20x20x2) - checked operation - O.K. |
| Unit ventilator (UV-1) Change air | Change air | Room 4026 | Room 4026 | 15/30/45 | Y/N | - replaced filters (20x20x2) - checked operation - O.K. |
| Unit Ventilator (old unit) | Trane | Room 4023 | Room 4023 | 15/30/45 | Y/N | - Filters clean - actuator not opening louvers |
| Unit ventilator | Trane | Room 4032 | Room 4032 | 15/30/45 | Y/N | - Filters clean - missing top filter - checked operation - O.K. |
| Unit ventilator | Trane | Room 4033 | Room 4033 | 15/30/45 | Y/N | - Storage room - unit excessively dirty |
| Unit ventilator | Trane | Room 4008 | Room 4008 | 15/30/45 | Y/N | - filters clean } Door insulation peeling - unit dirty |
| Unit ventilator | Trane | Room 4010 | Room 4010 | 15/30/45 | Y/N | - filters clean - Fan noisy - unit dirty - removed debris from fan |
| Unit ventilator | Trane | Room 4011 | Room 4011 | 15/30/45 | Y/N | - filters clean - unit dirty |
| Unit ventilator | Trane | Room 4013 | Room 4013 | 15/30/45 | Y/N | - filters clean - unit dirty |

mechanical operation

| HWDSB | SCHOOL: | Sir Winston Churchill | | | | Please Note: checked all unit's operation |
|--|----------------------------|--|---|----------------------------------|--|--|
| Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.) | Model | Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.) | Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.) | Time To Complete Check (minutes) | Requires Immediate Attention to maintain ventilation | Comments |
| Unit Ventilator | Trane | Room 4006 | Room 4006 | 15/30/45 | Y/N | - Filters clean - unit dirty (insulation peeling) |
| Unit Ventilator | Trane | Room 4005 | Room 4005 | 15/30/45 | Y/N | - Filters clean - unit dirty " |
| Unit Ventilator | Trane | Room 4004 | Room 4004 | 15/30/45 | Y/N | - Filters clean - unit dirty " |
| Unit Ventilator | Trane ^{Two units} | Room 4004 | Room 4004 | 15/30/45 | Y/N | - Filters clean - unit dirty |
| Unit Ventilator | Trane | Room 4002 | Room 4002 | 15/30/45 | Y/N | - Filters clean. - unit dirty. → BAS wires disconnected → Thermostat Damaged. |
| Unit Ventilator | Trane | Room 3027 | Room 3027 | 15/30/45 | Y/N | → Need Filter media - Dirty. |
| | | | | 15/30/45 | Y/N | |
| | | | | 15/30/45 | Y/N | |
| | | | | 15/30/45 | Y/N | |
| | | | | 15/30/45 | Y/N | |
| | | | | 15/30/45 | Y/N | |
| | | | | 15/30/45 | Y/N | |
| | | | | 15/30/45 | Y/N | |

| HWDSB | SCHOOL: | Sir Winston Churchill | | | | 1 of 5 |
|--|---------|--|---|----------------------------------|--|--|
| Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.) | Model | Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.) | Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.) | Time To Complete Check (minutes) | Requires Immediate Attention to maintain ventilation | Comments |
| UV | Trane | Room 1036 | Kitchen Class | 15/30/45 | Y/N | Clean and change filters test unit. |
| UV | Trane | Room 1027G | weight Class | 15/30/45 | Y/N | Clean and change filters. could only access 1 unit. test unit. |
| UV | Trane | Class 1030 | Class room | 15/30/45 | Y/N | Clean and change filter could not test / cage over thermostat |
| UV | Trane | Class 1028 | Class room | 15/30/45 | Y/N | Clean and change filters. test unit. |
| UV | Trane | class 2032 | Class room | 15/30/45 | Y/N | Clean and change filter. test unit. |
| UV | Trane | Class 2031 | Class Room | 15/30/45 | Y/N | Clean and change air filter. test unit. |
| UV | Trane | Class 2030 | Class room | 15/30/45 | Y/N | Clean and change air filter test unit. |
| UV | Trane | Class 2028 | Class room | 15/30/45 | Y/N | Clean and change air filter test unit. |
| UV | Trane | Class 2011 | Class room | 15/30/45 | Y/N | Clean and change air filter. 2 units in room needs parts. |
| UV | Trane | Class 2011 | class room | 15/30/45 | Y/N | Clean and change Air filter. test unit. |
| UV | Trane | Class 2022 | Class room | 15/30/45 | Y/N | Clean and change Air filters test unit. |
| UV | Trane | class 2017 | Class room | 15/30/45 | Y/N | Clean and change Air filters Test Unit. |
| UV | Trane | Class 2024 | Class Room | 15/30/45 | Y/N | Clean and change air filters Test Unit. |

| HWDSB | SCHOOL: | Sir Winston Churchill | | | | 2 of 5 |
|--|---------|--|---|----------------------------------|--|---|
| Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.) | Model | Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.) | Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.) | Time To Complete Check (minutes) | Requires Immediate Attention to maintain ventilation | Comments |
| UV | Trane | Office 2025 | Office | 15/30/45 | Y/N | Clean and replace Air filters Test Unit |
| UV | Trane | Office 2025 | Office | 15/30/45 | Y/N | Clean and replace Air f. Filters Test Unit |
| UV | Trane | Office 2025 | Office | 15/30/45 | Y/N | Clean and replace Air filters Test Unit |
| UV | Trane | Office 2025 | Office | 15/30/45 | Y/N | Clean and replace Air filters Test Unit |
| UV | Trane | Caf #1 1037 | Cafeteria | 15/30/45 | Y/N | Clean and replace filters test - not working |
| UV | Trane | Caf #2 1037 | Cafeteria | 15/30/45 | Y/N | Clean and replace filters test - Shorted |
| UV | Trane | Caf #3 1037 | Cafeteria | 15/30/45 | Y/N | Clean and replace filters no motor |
| UV | Trane | Caf #4 1037 | Cafeteria | 15/30/45 | Y/N | Clean and replace filters test - not working |
| UV | Trane | Caf #5 1037 | Cafeteria | 15/30/45 | Y/N | Clean and replace filters Test Unit |
| UV | Trane | Caf #6 1037 | Cafeteria | 15/30/45 | Y/N | Clean and replace filters test - not working |
| UV | Trane | Caf #7 1037 | Cafeteria | 15/30/45 | Y/N | Clean and replace filters test - not working |
| UV | Trane | Caf #8 1037 | Cafeteria | 15/30/45 | Y/N | Clean and replace filters test - Seized. |
| UV | Trane | Caf #9 1037 | Cafeteria | 15/30/45 | Y/N | Clean and replace filters Test - not working. |

| HWDSB | SCHOOL: | Sir Winston Churchill | | | | 3 of 5 |
|--|---------|--|---|----------------------------------|--|--|
| Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.) | Model | Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.) | Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.) | Time To Complete Check (minutes) | Requires Immediate Attention to maintain ventilation | Comments |
| Uv | Trane. | Laft #10 1037 | Cafeteria | 15/30/45 | Y/N | Clean and replace filters test - not working |
| Uv | Trane | Class 3007 | Class Room | 15/30/45 | Y/N | Clean and replace filters test unit. |
| Uv | Trane | Class 3006 | Class Room | 15/30/45 | Y/N | Clean and replace filters test unit. |
| Uv | Trane | Class 3009 | Class Room | 15/30/45 | Y/N | Clean and replace filters. test unit |
| Uv | Trane | Class 3005 | Class Room | 15/30/45 | Y/N | Clean and replace filters no power to thermostat. |
| Uv | Trane | Class 3010 | Class Room | 15/30/45 | Y/N | Clean and replace filters test unit. |
| Uv | Trane | Class 3004 | Class room | 15/30/45 | Y/N | Clean and replace filters no power to the thermostat |
| Uv | Trane | Class 3011 | Class room | 15/30/45 | Y/N | Clean and replace filters 2 units in room 1 - not working |
| Uv | Trane | Class 3011 | Class Room | 15/30/45 | Y/N | Clean and replace filters 2 units 1 - working |
| Uv | Trane | Class 3023 | Class Room | 15/30/45 | Y/N | Clean and replace filters. test unit |
| Uv | Trane | Class 3015 | Class room | 15/30/45 | Y/N | Clean and replace filters no power to thermostat |
| Uv | Trane | Class 3030 | Class room | 15/30/45 | Y/N | Clean and replace filters. test unit |
| Uv | Trane | Class 3017 | Class room | 15/30/45 | Y/N | Clean and replace filters Test Unit |

| HWDSB | SCHOOL: | | | | | |
|--|---------|--|---|----------------------------------|--|---|
| Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.) | Model | Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.) | Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.) | Time To Complete Check (minutes) | Requires Immediate Attention to maintain ventilation | Comments |
| Uv | Trane | Class 3024 | Class Room | 15/30/45 | Y/N | Clean and replace filters test unit. |
| Uv | Trane | Class 3018 | Class Room | 15/30/45 | Y/N | Clean and replace filters test unit. |
| Uv | Trane | Class 3031 | Class Room | 15/30/45 | Y/N | Clean and replace filters test unit. |
| Uv | Trane | Class 3028 | Class Room | 15/30/45 | Y/N | Clean and replace filters no power to thermostat |
| Uv | Trane | Class 3025 | Class Room | 15/30/45 | Y/N | Clean and replace filters No power to thermostat. |
| Uv | Trane | Class 3022 | Class Room | 15/30/45 | Y/N | Clean and replace filters. test unit. / Bad bearings. |
| Uv | Trane | Class 3033 | Class Room | 15/30/45 | Y/N | Clean and replace filters test unit. |
| Uv | Trane. | Class 3026 | Class Room | 15/30/45 | Y/N | Clean and replace filters test unit. |
| Uv | Trane | Class 3027 | Class Room | 15/30/45 | Y/N | Clean and replace filters test unit. |
| Uv | Trane | Class 4002 | Class Room | 15/30/45 | Y/N | Clean and replace filters thermostat Broken |
| Uv | Trane | Class 4004 | Class Room | 15/30/45 | Y/N | Clean and replace filters test unit. |
| Uv | Trane | Class 4010 | Class Room | 15/30/45 | Y/N | Clean and replace filters test unit. |
| Uv | Trane | Class 4013 | Class Room | 15/30/45 | Y/N | Clean and replace filters test unit. |

| HWDSB | SCHOOL: | 5 of 5 | | | | |
|--|------------------|--|---|----------------------------------|--|---|
| Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.) | Model | Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.) | Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.) | Time To Complete Check (minutes) | Requires Immediate Attention to maintain ventilation | Comments |
| Uv | Trane | Class 4008 | Class room | 15/30/45 | Y/N | Clean and replace filters test unit. |
| Uv | Trane | Class 4005 | Class room | 15/30/45 | Y/N | Clean and replace filters test unit. |
| Uv | Trane | Class 4003 | Class room | 15/30/45 | Y/N | Clean and replace filters 2 units in room 1 - works |
| Uv | Trane | Class 4003 | Class room | 15/30/45 | Y/N | Clean and replace filters 2 units in room 1 - does not work |
| Uv | Trane | Class 4006 | Class room | 15/30/45 | Y/N | Clean and replace filters. test units. |
| Uv | Trane | Class 4011 | Class room | 15/30/45 | Y/N | Clean and replace filters test units |
| Uv | Trane | Class 4033 | Class room | 15/30/45 | Y/N | Clean and replace filters motor unplugged. |
| Uv | Trane | Class 4032 | Class room | 15/30/45 | Y/N | Clean and replace filters. test units |
| Uv | Trane | Class 4023 | Class room | 15/30/45 | Y/N | Clean and replace filters test units. |
| Uv | Trane | Class | class room | 15/30/45 | Y/N | |
| | | | | 15/30/45 | Y/N | |
| | | | | 15/30/45 | Y/N | |
| | | | | 15/30/45 | Y/N | |