

HWDSB	SCHOOL:	Viscount Montgomery				Cont'd	1 of 3
Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.)	Model U.V.#	Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.)	Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.)	Time To Complete Check (minutes)	Requires Immediate Attention to maintain ventilation.	Comments	
Unit ventilator	Trane (1500) UV8	Room 122	music Rm.	15/30/45	Y/N	- Filters clean - checked operation → o.k.	
Unit ventilator	Trane (1500) UV9	Room 124	class room	15/30/45	Y/N	- filters clean - checked operation → o.k.	
Unit ventilator	Trane (1500) UV10	Room 120	science Lab	15/30/45	Y/N	- filters clean, checked operation → o.k.	
Unit ventilator	Trane (1500) UV11	Room 126	class room	15/30/45	Y/N	- filters clean, checked op. → o.k.	
Unit ventilator	Trane (1500) UV12	Room 127	Gym storage	15/30/45	Y/N	- filters clean, checked operation → o.k.	
Unit ventilator	Trane (1500) UV14	Room 126	Class Rm.	15/30/45	Y/N	- filters clean, checked operation, o.k.	
Unit ventilator	Trane (1500) UV18	Room 134	Staff Room	15/30/45	Y/N	- filters clean, checked operation → o.k.	
Unit ventilator	Trane (1250) UV17	Room 132	Class Room	15/30/45	Y/N	- filters clean, checked operation → o.k.	
Unit ventilator	Trane (1500) UV7	Room 108	Class Room	15/30/45	Y/N	- replaced filters, checked operation → o.k.	
Unit ventilator	Trane (1500) UV5	Room 109	Class Room	15/30/45	Y/N	- replaced filters - checked operation → o.k.	
Unit ventilator	Trane (1500) UV3	Room 110	Class Room	15/30/45	Y/N	- replaced filters - checked operation.	
Unit ventilator	Trane (1500) UV4	Room 112	Class room	15/30/45	Y/N	- replaced filters - checked unit operation, o.k.	
Unit ventilator	Trane (1500) UV6	Room 113	Class Room	15/30/45	Y/N	- replaced filters - checked unit → o.k.	

⇒ All filters replaced found on site. (Caretaking staff maintains units well!)

HWDSB	SCHOOL:	Viscount Montgomery				2 of 3	cont'd
Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.)	Model	Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.)	Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.)	Time To Complete Check (minutes)	Requires Immediate Attention to maintain ventilation	Comments	
E.F-1	Greencheck G-123-V6-X	South East Roof SW	Girls washroom Rooms 110, 112	15/30/45	Y/N	- checked operation → o.k.	
E.F-2	Greencheck G-123-V6-X	Roof SW	Room 109, 113	15/30/45	Y/N	- checked operation → o.k.	
E.F-3	Greencheck G-123-V6-X	Roof S.W	Room 108, 115	15/30/45	Y/N	- checked operation → o.k.	
E.F-4	Greencheck G-183-V6-10-X	Roof SW	Rooms 104, 105A, 107	15/30/45	Y/N	- checked operation → o.k.	
E.F-5	Power Ventilator DX11B	Roof S.W	Rooms 120, 121, 125, 126	15/30/45	Y/N	- BAS enabled - not working.	
E.F-6	Greencheck G-123-V6-X	Roof centre Roof	Rooms 122, 125	15/30/45	Y/N	- checked operation → o.k.	
E.F-7	Greencheck GB-200-HP-20-X	Roof centre Roof	Rooms 103, 128	15/30/45	Y/N	- checked operation → o.k.	
E.F-8	Greencheck G-123-V6-X	Roof South centre	Rooms 129, 152	15/30/45	Y/N	- BAS Enabled - not working	
E.F-9	Greencheck G-123-V6-X	Roof southeast	145, 143 Rooms	15/30/45	Y/N	- BAS Enabled - Not working	
E.F-10	Greencheck G-123-V6-X	Roof	Kindergarten, Washrooms	15/30/45	Y/N	- checked operation → o.k.	
E.F-11	Power Ventilator DX11B	Roof South east	North east	15/30/45	Y/N	- checked operation → o.k.	
E.F-13	Greencheck G-123-V6-X	Roof N/East	Rooms 132, stage, staff.	15/30/45	Y/N	- BAS Enabled → not running	
E.F-12	Greencheck G-123-V6-X	Roof S/East	Rooms 148, 150, 151	15/30/45	Y/N	- checked operation → o.k.	
AHV	Sturtevant (Never Runs)	Room 135B	Auditorium	45	YES	→ FAN BEARS loud, Not working → Asbestos wrapped	

HWDSB	SCHOOL:	Viscount Montgomery 3063 Cont'd:				
Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.)	Model	Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.)	Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.)	Time To Complete Check (minutes)	Requires Immediate Attention to maintain ventilation	Comments
EF-14	Green check G123-V6-X	Roof North East	North East Room 134, 135	15/30/45	Y/N	- checked operation → o.k
EF	Greencheck G-123-V6-X	Roof (North East)		15/30/45	Y/N	- checked operation. → o.k
* E.F	NO. INFO. Two Units	Wall	Gym	15/30/45	Y/N	Gym wall exhaust, one broken. checked operation - only one operating
Unit Ventilator	Change Air U.V.2	Room 115	Kindergarten	15/30/45	Y/N	- checked operation, Filters clean.
Unit Ventilator	Change Air U.V.1	Room 140	Library	15/30/45	Y/N	- filters clean, checked operation - No cooling - possible condenser leak.
Unit Ventilator	Trane (1500) U.V.20	Room 142	Computer class Room	15/30/45	Y/N	- filters clean, checked operation → o.k.
Unit Ventilator	Trane (1500) U.V.21	Room 143	Class Room	15/30/45	Y/N	- replaced filters, checked operation → o.k
Unit Ventilator	Trane (1500) U.V.19	Room 147	Classroom	15/30/45	Y/N	- filters replaced, checked operation → o.k
Unit Ventilator	Trane (1500) U.V.22	Room 146	Class room	15/30/45	Y/N	- filters replaced, checked operation → o.k.
Unit Ventilator	Trane (1500) U.V.13	Room 103	Class room	15/30/45	Y/N	- filters replaced checked operation → o.k.
Unit Ventilator	Trane (1500) U.V.15	Room 129	Class room	15/30/45	Y/N	- filters clean, checked operation → o.k.
Unit Ventilator	Trane (1500) U.V.16	Room 152	Class room	15/30/45	Y/N	- filters clean, checked operation → o.k.
Unit Ventilator	Trane (1500) U.V.23	Room 145	class room	15/30/45	Y/N	- filters clean, checked operation → o.k.

NO Blades

monday

HWDSB	SCHOOL:	Viscount Montgomery				
Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.)	Model	Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.)	Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.)	Time To Complete Check (minutes)	Requires Immediate Attention to maintain ventilation	Comments
	W.H. Ballard School			15/30/45	Y/N	
A/c	Kenmore	window	Room 128	15/30/45	Y/N	- needs cleaning
A/c	Kenmore	window	Room 208	15/30/45	Y/N	- Noisy fan - not cooling needs replaced.
A/c	Panasonic	window	Room 210	15/30/45	Y/N	- needs cleaning
				15/30/45	Y/N	
	Viscount Montgomery School			15/30/45	Y/N	
A/c	climette		Room 153	15/30/45	Y/N	working
A/c	climette-aire		Room 140	15/30/45	Y/N	- not cooling. - needs replaced.
A/c	climette-air.		Room 142	15/30/45	Y/N	- working.
				15/30/45	Y/N	* Unit vent #1 not cooling.
				15/30/45	Y/N	(as per caretaker).
				15/30/45	Y/N	
				15/30/45	Y/N	