

6/15/2015

HWDSB		SCHOOL: West Dale Secondary School				
Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.)	Model	Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.)	Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.)	Time To Complete Check (minutes)	Requires Immediate Attention to maintain ventilation	Comments
Power ventilator	Greencheck CUE-161-V6-5X	4th Floor Roof west	Science Room 3020	15/30/45	Y/N	- checked operation - o.k
Power ventilator	Greencheck CUE-101-V6-4X	4th floor Roof west	Rm 3019	15/30/45	Y/N	- checked operation - o.k
Power ventilator	Greencheck CUE-161-V6-5X	4th floor Roof west	Rm 303 3012 A	15/30/45	Y/N	- checked operation - o.k
Power ventilator	Greencheck CUE-101-V6-4X	4th floor Roof west	Rm 3012	15/30/45	Y/N	- checked operation - o.k
Power ventilator	Greencheck CUE-101-V6-4X	4th floor Roof west	Rm 2009	15/30/45	Y/N	- checked operation - o.k
Power ventilator	Greencheck CUE-101-V6-4X	4th floor Roof west	Science Room 2011	15/30/45	Y/N	- checked operation - o.k
Power ventilator	Greencheck CUE-101-V6-4X	4th floor Roof west	Rm 2016	15/30/45	Y/N	- checked operation - o.k
Power ventilator	Greencheck CUE-101-V6-4X	4th floor Roof west	2017 Rm	15/30/45	Y/N	- checked operation - o.k
E.F	Dome Fan (Painted)	4th floor East roof	Shop?	15/30/45	Y/N	- Bearings worn - fan shakes. - checked operation - o.k
E.F	Dome Fan (Painted)	4th floor East roof	Bathrooms	15/30/45	Y/N	- checked operation - o.k.
E.F	Dome Fan (Painted)	4th floor west roof	1st Lady + men Staff Rm. Slop sinks	15/30/45	Y/N	- Excessive vibration (Bearings) - working.
EF #49	Dome fan	4th floor west roof	South west slop sinks	15/30/45	Y/N	- Not Running
EF #6	Dome fan	4th floor west roof	Rm 303	15/30/45	Y/N	- Not Running

DX Cooling

45 min.

HWDSB	SCHOOL:	West Dale Secondary School				
Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.)	Model	Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.)	Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.)	Time To Complete Check (minutes)	Requires Immediate Attention to maintain ventilation	Comments
Power ventilator	- No label/rating plate found	4th floor west roof	?	15/30/45	Y/N	- Not running
Power ventilator	- No rating plate found.	4th floor west roof	?	15/30/45	Y/N	- Not running.
E.F. #31	Dome Fan (No label)	4th floor west roof	South west General	15/30/45	Y/N	- Not running.
				15/30/45	Y/N	
				15/30/45	Y/N	
				15/30/45	Y/N	
				15/30/45	Y/N	
				15/30/45	Y/N	
				15/30/45	Y/N	
				15/30/45	Y/N	
				15/30/45	Y/N	
				15/30/45	Y/N	
				15/30/45	Y/N	

Alex

HWDSB	SCHOOL:	Westdale High School				
Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.)	Model	Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.)	Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.)	Time To Complete Check (minutes)	Requires Immediate Attention to maintain ventilation	Comments
Unit ventilator	Engineered Air VUV-800	Room	Room 2011	15/30/45	Y/N	Please Note: All inlet screens are dirty. (located under filters when Louvres are opened.)
U.V.	Eng. Air VUV-800	Room	Room 2016	15/30/45	Y/N	
U.V	Eng. Air VUV-800	Room	Room 2016 A	15/30/45	Y/N	
U.V	Eng. Air VUV-800	Room	Room 2017	15/30/45	Y/N	
U.V	Eng. Air VUV-800	Room	Room 2009	15/30/45	Y/N	Two units in room 2009
U.V	Eng. Air VUV-800	Room	Room 2009	15/30/45	Y/N	
U.V	Eng. Air VUV-800	Room	Room 3020	15/30/45	Y/N	Two units in room 3020
U.V	Eng. Air VUV-800	Room	Room 3020	15/30/45	Y/N	
U.V	Eng. Air VUV-800	Room	Room 3019	15/30/45	Y/N	- condensate drain condensate drain broken. @ drain pan
U.V	Eng. Air VUV-800	Room	Room 3019	15/30/45	Y/N	- missing inlet air screen.
U.V	Eng. Air VUV-800	Room	Room 3012	15/30/45	Y/N	Two units in room 3019
				15/30/45	Y/N	
				15/30/45	Y/N	

HWDSB	SCHOOL:	Westdale Secondary School				
Unit Type and Tag (HVAC, AHU, EF, MAU, SF, etc.)	Model	Unit Loc. (Roof, Penthouse, Boiler Room, Corridor, etc.)	Serves (Offices, Foyer, Library, Staff Room, Classroom, Washroom, etc.)	Time To Complete Check (minutes)	Requires Immediate Attention to maintain ventilation	Comments
RTU 2	Trane Voyager VCD211CWLABA	Roof 4th Floor	Classrooms	15/30/45	Y/N	Checked filters, belts, operation, -O.K.
RTU 1	Trane Voyager YCD151C WHAAA	Roof 4th Floor	Resource Room	15/30/45	Y/N	- O.K. "checked filters, belts, operation.
RTU 3	Trane Voyager VCD103CWC AAB	Roof 4th floor	Art Room	15/30/45	Y/N	- O.K. checked, filters, belts, operation
RTU 4	Trane Voyager YCH301C584 D	Roof 4th floor	music Room	15/30/45	Y/N	- O.K. checked filters, belts, operation
RTU	Carrier -101JA 4H8GF028AC	Roof 3rd floor	cafeteria	15/30/45	Y/N	- O.K. checked filters, belts, operation
RTU	Carrier 48HGF02YAB -101JA	Roof 3rd floor	Library	15/30/45	Y/N	- O.K. checked filters, belts, operation
AHU 1	Engineered Air LM-15-C	Boiler Room	Auditorium	15/30/45	Y/N	- O.K. checked filters, belts, operation
AHU 2	Engineered Air	Duplicating Room	Admin. office	15/30/45	Y/N	- O.K. checked filters, belts, operation !!
AHU	Engineered Air LM-15-C	Boiler Room	Gym	15/30/45	Y/N	- Not on list - Replaced 12x24x2 Filters. - Need 24x12x2 filters
				15/30/45	Y/N	
				15/30/45	Y/N	
				15/30/45	Y/N	
				15/30/45	Y/N	